

# **MICRO SYSTEMS**

**FIELD  
BULLETINS**



Four-Phase Systems

November 06, 1983

MICROSYSTEM PRODUCT FIELD BULLETINS

You have been selected to be on the mailing list of Microsystems Product Field Bulletin (MPFB). MPFB previously was known as the Early Warning TWX system. The idea is to start fresh, reissue all the old EWT's, add those that were to go into the system, and update the information contained in them.

The numbering scheme has also undergone a change. Instead of the old file system, all MPFB's will be in semi-chronological order, with two indexes used for quick reference. The "semi-chronological" order results from a functional grouping of the old MPFB's and chronologically adding all new MPFB's.

The first index is a table of contents. This gives a one line description of each MPFB, its number and the date it was submitted. The second index is designed to act as a cross-reference, signifying all MPFB's that relate to a particular product.

If you have any questions, information, MPFB's you would like to submit (or see), would like to add names to the mailing list; or would like to subtract your name from the list, please call Field Engineering, Tempe Operations at (602) 829-3100. Ask for the Microsystems Product Field Bulletin Coordinator.

I hope this proves to be an effective vehicle for disseminating information to those concerned.

This information is designed for use by Motorola Employees only. And is not to be transmitted to customers. Abuse may restrict the availability of future information.

Any suggestions on the format, the cross reference or other ideas that would make MPFB more useful to you, are encouraged.

Sincerely yours;  
MPFB Coordinator

SK/kf



MICROSYSTEMS PRODUCT FIELD BULLETINS

UPDATE-(11/03/83)

Enclosed are a new round of Microsystems Product Field Bulletins (MPFB). The packet consists of an updated index and cross index to replace the earlier indexes, and MPFB's 0047-0066.

This information is designed for use to Motorola employees only. And is not to be transmitted to customers. Abuse may restrict the availability of future information.

If you have any questions, or suggestions on the format, or have any MPFB's you would like to submit (or see), please call Field Engineering, Tempe Operations at (602) 829-3100. Ask for the MPFB Coordinator.

Sincerely Yours,  
MPFB Coordinator  
SK/bd

MICROSYSTEMS PRODUCT  
FIELD BULLETIN  
\*\*\*CONFIDENTIAL\*\*\*

Date: April 16, 1982

MPFB 0001

Product Type: CDC 300 MB Hard Disk

Contributed By: MQ

Contact: Hardware Specialist  
Field Engineering  
Tempe Operations  
(602) 829-3100

Information Type:  As Needed  
 Mandatory  
 Information Only

\*\*\*\*\*

Symptom / Problem

CDC 300 HARD DISK INSTALL ON EXORMACS

It has been brought to my attention that there are some questions concerning installation of the CDC 300 Mb Hard Disk on the EXORMacs. Here are a few things to check for when installing it;

\*\*\*\*\* NOTE : Remember, we are not responsible for installation of this disk, and we do not support the 300 Mb, but if you find yourself in this situation, then maybe these things will help.

- 1.) Should be set for 64 Sectors per track. Remember!!, sector numbering is from 1-64, not 0-63... A06 board.
- 2.) If disk is daisy chained with another type there is a switch to select this in the disk.
- 3.) If installing on a system that is running 2.1 VERSAdos, it will work, but the new release of 3.0 VERSAdos is designed for use with this drive, and will probably work much better.

\*\*\*\*\* Note : The CDC F.E. will usually set up the drive and test it on a FTU, make sure you tell him what to set it up like, all you will have to do is connect the cables and initialize it...

MICROSYSTEMS PRODUCT  
FIELD BULLETIN  
\*\*\*CONFIDENTIAL\*\*\*

Date: April 22, 1982

MPFB 0002

Product Type: 32-96 MB. Hard Disk

Contributed By: CH

Contact: Hardware Specialists  
Field Engineering  
Tempe Operations  
(602) 829-3100

Information Type:  As Needed  
 Mandatory  
 Information Only

\*\*\*\*\*

Symptom / Problem

CDC 300 HARD DISK CHANGES

For Information only;

You will find a few changes in the Hard Disks that you install in the field from now on, they are as follows:

There are no longer screws securing the Electronics Module under the Disk Chassis, there are only two(2) screws in the hinge of the module. Also be careful, the new Electronics Modules are being made of plastic, and the Absolute filter has now got a Velocity sensor attached to the top of it. As of now these are the only thing that have changed...

MICROSYSTEMS PRODUCT  
FIELD BULLETIN  
\*\*\*CONFIDENTIAL\*\*\*

Date: April 15, 1983

MPFB 0003

Product Type: CMD DRIVE

Contributed By: PT

Contact: Hardware Specialists  
Field Engineering  
Tempe Operations  
(602) 829-3100

Information Type:  As Needed  
 Mandatory  
 Information Only

\*\*\*\*\*

Symptom / Problem

BYPASSING THE CDC INTERLOCKS

The interlocks have been changed in the new CDC CMD disk drives, and there is a way around the interlocks of both disk drives for troubleshooting purposes.

\*\*\*\*\*

Solution / Fix

The deckdown switch has been moved and redesigned. Instead of a physical switch like the old ones have, the new deckdown switch is a magnetic pickup switch and comes together when the deck is closed (this switch is located on the bottom center of the deck). You can test the interlock circuit by disconnecting the four wire plug going into the front panel board and shorting pin 3 to pin 4 (of the plug).

\*\*\*\* NOTE \*\*\*\* NO NOT ALLOW HEADS TO LOAD ON A DRIVE THAT HAS THE INTERLOCKS REMOVED FROM THE CIRCUIT

Two other changes: (1) They moved the pack in place switch, from the left rear of housing to the right side of the housing; (2) They added an air flow sensor that detects the amount of air flow out of the absolute filter (and there is what looks like a set screw in the air line between the absolute filter and the switch.)

MICROSYSTEMS PRODUCT  
FIELD BULLETIN  
\*\*\*CONFIDENTIAL\*\*\*

Date: November 16, 1982

MPFB 0004

Product Type: EXORDisk II / III

Contributed By: TE

Contact: Software Specialists  
Field Engineering  
Tempe Operations  
(602) 829-3100

Information Type:  As Needed  
 Mandatory  
 Information Only

\*\*\*\*\*

Symptom / Problem

BYPASSING THE CDC INTERLOCKS

Some customers are changing MDOS boot ROMS, to replace Parallel Printer Drivers with Serial Printer Drivers. The last two (2) bytes (VERSION NUMBER and DRIVE TYPE) must NOT be changed or the FORMAT command will fail. This applies to all Floppy Disk units running under MDOS... Beware!! Its also possible under XDOS...



MICROSYSTEMS PRODUCT  
FIELD BULLETIN  
\*\*\* CONFIDENTIAL \*\*\*

Date: September 14, 1983

MPFB 0005

Product Type: HDS-400 on VERSAdos 4.21

Contributed By: MM

Contact: Software Specialists  
Field Engineering  
Tempe Operations  
(602) 829-3100

Information Type:   x   As Needed  
       Mandatory  
       Information Only

\*\*\*\*\*

Symptom / Problem

MULTI-DROP HDS-400 ON EXORMACS

In an EXORMacs Multi-drop environment, each HDS-400 that is not in transparent mode to the EXORMacs requires a separate copy of the program 'GHOST' to be resident in memory. The GHOST program requires approximately 100K bytes (decimal), including buffer areas. The newsletter refers to two patches to help save space by: (1) reducing the size of the data area, and, (2) allowing the executable portion of GHOST to be shareable.

>>> CONTRARY TO THE NEWSLETTER only the first patch is applicable to the released version of the GHOST software. The released GHOST program was linked in such as way that program and data share the same segment.

Future releases should have both these changes incorporated.

\*\*\*\*\*

Solution / Fix

(1) Reduce the size of the data area:  
      =PATCH GHOST.LO  
      11F58  
      20                  (was \$60)  
      .  
      Q

NOTE: The reference to two patches may have only been in early versions of the customer newsletter. Later versions included the above patch.

MICROSYSTEMS PRODUCT  
FIELD BULLETIN  
\*\*\*CONFIDENTIAL\*\*\*

Date: October 15, 1983

MPFB 0006

Product Type: EXORmacs

Contributed By: RC & SK

Contact: Hardware Specialists  
Field Engineering  
Tempe Operations  
(602) 829-3100

Information Type:  As Needed  
 Mandatory  
 Information Only

\*\*\*\*\*

Symptom / Problem

EXORMACS BOARD REV LEVELS AS OF 10/15/83

This should come in hand. Here is a list of the most up to date  
EXORmacs Rev levels, as of 10/15/83...

Debug - New Style A - P  
          Old Style Z - AS  
Mpu     - BA  
Mem     - (128K) AR -- AW  
          (256 & 512) S  
Dim     - AP  
Uipc    - AB - AM  
Mccm    - BG - BH  
FDC     - BK

MICROSYSTEMS PRODUCT  
FIELD BULLETIN  
\*\*\*CONFIDENTIAL\*\*\*

Date: June 4, 1982

MPFB 0007

Product Type: EXORmacs Debug Board

Contributed By: PT

Contact: Hardware Specialists  
Field Engineering  
Tempe Operations  
(602) 829-3100

Information Type:  As Needed  
 Mandatory  
 Information Only

\*\*\*\*\*

Symptom / Problem

MAINTENANCE DOCUMENTATION ERROR

All of the maintenance manuals show the different types of ROM chips that can be used on this board. However, there is no Pins 11 and 12; therefore, only the TMS2716 chip can be used.

Documentation will correct this problem in the new manuals.

MICROSYSTEMS PRODUCT  
FIELD BULLETIN  
\*\*\*CONFIDENTIAL\*\*\*

Date: June 9, 1982

MPFB 0008

Product Type: M68KDM

Contributed By: MQ

Contact: Hardware Specialists  
Field Engineering  
Tempe Operations  
(602) 829-3100

Information Type:  As Needed  
 Mandatory  
 Information Only

\*\*\*\*\*

Symptom / Problem

KDM TO MCCM ON EXORMACS

Beware... When connecting a KDM board to a MCCM port when under 3.0 VERSAdos, the new software is such that you will not be able to communicate with the EXORMacs in transparent mode. Unless you do the following:

- 1.) Jumper pins #4 and #5 together on one end of the RS-232 "D" Connector.
- 2.) If using the M68KDM Users Guide, it will show how to enter the command to download from the EXORMacs. Don't enter it that way. Do it this way:

READ ;x=COPY FILENAME.MX,#CNxx

where xx = EXORMacs Port Number

MICROSYSTEMS PRODUCT  
FIELD BULLETIN  
\*\*\* CONFIDENTIAL \*\*\*

Date: August 30, 1982

MPFB 0009

Product Type: EXORMacs W/ 3.0 VERSAdos

Contributed By: MQ

Contact: Hardware Specialists  
Field Engineering  
Tempe Operations  
(602) 829-3100

Information Type:   x   As Needed  
       Mandatory  
       Information Only

\*\*\*\*\*

Symptom / Problem

KDM TO MCCM ON EXORMACS

Beware... When installing VM11-2 Memory boards (512K) into the EXORMacs Chassis, be sure to address the 512K board at 00000. Add any 128K ram after all the 512K's. There is a problem with Bus Trap Errors when the 512K boards are after the 128K's. Also, remember to remove the bus arbitration jumpers in front of the 512K's.

MICROSYSTEMS PRODUCT  
FIELD BULLETIN  
\*\*\*CONFIDENTIAL\*\*\*

Date: May 17, 1982

MPFB 0010

Product Type: VERSAdos 3.0

Contributed By: MM

Contact: Hardware Specialists  
Field Engineering  
Tempe Operations  
(602) 829-3100

Information Type: \_\_\_ As Needed  
                  \_\_\_ Mandatory  
                  \_\_\_ Information Only

\*\*\*\*\*

Symptom / Problem

VERSADOS 3.0 LIST UTILITY PATCH

The VERSAdos 3.0 LIST command causes the first line of text to be appended to the header line on each new page if the output was being sent to an MCCM port. The following patch is found in an Addendum to M68000 VERSAdos SYSTEM FACILITIES REFERENCE MANUAL, M68KVSP(A1).

\*\*\*\*\*

Solution / Fix

```
=PATCH LIST.LO
M 0
'042682 3'
.
M 1250;DI
  BSR.L $13EE
.
M $13EE;DI
  MOVE.L $2F6(PC),D1
  PEA $274(PC)
  SUB.L (A7)+,D1
  RTS
.
Q
=END
```

MICROSYSTEMS PRODUCT  
FIELD BULLETIN  
\*\*\*CONFIDENTIAL\*\*\*

Date: May 17, 1982

MPFB 0011

Product Type: VERSAdos 3.0

Contributed By: MM

Contact: Software Specialists  
Field Engineering  
Temp Operations  
(602) 829-3100

Information Type:  As Needed  
 Mandatory  
 Information Only

\*\*\*\*\*

Symptom / Problem

VERSADOS 3.0 SPOOLER UTILITY PATCH

Following are patches to: (1) eliminate the banner in the spooler and, (2) eliminate the automatic form feed every time the printer is assigned. These should be useful for those customers wanting to cut down on the amount of paper being produced by VERSAdos 3.0

\*\*\*\*\*

Solution / Fix

```
=PATCH SPL.LO
1B7E
4E75          (WAS 41EC)
.
1DDE
42804E75     (WAS 082C0005)
.
Q
=PATCH VERSADOS.SY
09900        (START OF .PRT)
24E
60           (WAS 66)
.
Q
=END
```

MICROSYSTEMS PRODUCT  
FIELD BULLETIN  
\*\*\*CONFIDENTIAL\*\*\*

Date: May 17, 1982

MPFB 0012

Product Type: 68K SYMBUG/A

Contributed By: MM

Contact: Software Specialists  
Field Engineering  
Tempe Operations  
(602) 829-3100

Information Type:     As Needed  
    Mandatory  
  x   Information Only

\*\*\*\*\*

Symptom / Problem

68K SYMBUG PATCH

Usage of the TASK command causes the task note level to be changed unpredictably regardless of the note level specified in the command (if any). The note level is usually changed to a value that cannot be displayed with the STAT command. The result of the bug is usually that set breakpoints will not be enabled at execution time. (This problem with 68K SYMBUG/A 2.00 is written up in SPR #282).

\*\*\*\*\*

Solution / Fix

```
=PATCH SYMBUG
M 44AA;DI
  CMP.B  #1,D0
  BEQ.S  **6
  MOVE.W D2,28(A4)
  BSR   $3E94
.
Q
=END
```



MICROSYSTEMS PRODUCT  
FIELD BULLETIN  
\*\*\*CONFIDENTIAL\*\*\*

Date: August 30, 1982

MPFB 0013

Product Type: VERSAdos 3.0

Contributed By: MM

Contact: Software Specialists  
Field Engineering  
Tempe Operations  
(602) 829-3100

Information Type:   x   As Needed  
       Mandatory  
       Information Only

\*\*\*\*\*

Symptom / Problem

VERSADOS 3.0 .FHS CALL TO RECEIVE LU PATCH

The VERSAdos 3.00 '.FHS' call to receive Logical Units will not work unless the task is a system task.

\*\*\*\*\*

Solution / Fix

```
=PATCH VERSADOS.SY  
O $5800  
M 9FA;DI  
  BNE.S *+ $1A  
  
.  
Q  
=END
```

MICROSYSTEMS PRODUCT  
FIELD BULLETIN  
\*\*\*CONFIDENTIAL\*\*\*

Date: September 1, 1982

MPFB 0014

Product Type: VERSAdos 3.0 SYSGEN

Contributed By: MM

Contact: Software Specialists  
Field Engineering  
Tempe Operations  
(602) 829-3100

Information Type:   x As Needed  
       Mandatory  
       Information Only

\*\*\*\*\*

Symptom / Problem

VERSADOS 3.0 SYSGEN CORRECTIONS

The VERSAdos 3.0 SYSGEN file IOC.SA has several errors which are: (1) you can't sysgen for 0 local printers on the debug board, (2) you can't sysgen for two UDC's and, (3) you can't sysgen for the four local terminals sysgen allows for.

The following corrections to IOC.SA will correct these problems. These patches refer to line numbers run on the standard IOC.SA file that has had a listing made with the command,

=LIST IOC.SA,#PR;L=1000

thus making a similar listing is required for these patches.

\*\*\*\*\*  
Solution / Fix

- |                     |              |  |
|---------------------|--------------|--|
| (1) Following line: | 1283         | ENDC , add the following line<br>ENDC                          |
| (2) Change line:    | 1285<br>1285 | IFNE /NOLPRT-1 , to<br>IFGT /NOLPRT-1                          |
| (3) Change line:    | 1343<br>1343 | IFNE /NOLPRT-1 , to<br>IFGT /NOLPRT-1                          |
| (4) Delete line:    | 1346         | ENDC   |
| (5) Change line:    | 1357<br>1357 | IFGT /NOLTERM-2 , to<br>IFGT /NOLTERM-3                        |
| (6) Change line:    | 1395<br>1395 | CCB 'CRD1',XTIPCA,254, .... , to<br>CCB 'CRD2',XTIPCA,254, ... |

MICROSYSTEMS PRODUCT  
FIELD BULLETIN  
\*\*\*CONFIDENTIAL\*\*\*

Date: September 3, 1982

MPFB 0015

Product Type: Data I/O System 29

Contributed By: CH

Contact: Software Specialists  
Field Engineering  
Tempe Operations  
(602) 829-3100

Information Type:   x   As Needed  
       Mandatory  
       Information Only

\*\*\*\*\*

Symptom / Problem

DATA I/O 29 PERSONNEL CONTACT

If you run into a situation that a customer has a Data I/O Prom Programmer System 29, and is experiencing problems, they should get in contact with Steve Montgomery at 800-426-1045. Data I/O System 19 works ok. This in regards to using the System 29 with the EXORmacs PP1 software (PROM Programmer

MICROSYSTEMS PRODUCT  
FIELD BULLETIN  
 \*\*\*CONFIDENTIAL\*\*\*

Date: September 14, 1982

MPFB 0016

Product Type: Data I/O System 29

Contributed By: MM

Contact: Software Specialists  
 Field Engineering  
 Tempe Operations  
 (602) 829-3100

Information Type:   x   As Needed  
       Mandatory  
       Information Only

\*\*\*\*\*  
 Symptom / Problem                      VERSADOS 2.1 & 3.0 HARDWARE INFO LOCATION

Patch locations for the Multi-user Hard Disk version of Vdos 3.0 and Vdos 2.1

<u>Name</u>	<u>Vdos 2.1</u>	<u>Vdos 3.0</u>	
CN00	15CBC	17376	For Terminal Hardware information, see M68KSYSGEN(D2), pg 5-6, Example; To change terminal to 1200 baud, change the zeros to \$8E070050.
CN01	1572A	173F4	
Pr1	Debug	172F4	
CN10	14F74	16F80	For 703 Centronics, the printer word should be Zeros, for B-600 models it should be \$80010A00.
CN11	14FE2	16FFE	
CN12	15050	1707C	Used for security, see Facilities manual, M68KVSF(D1), Pg 5-10, for a description of what to do with &EET, in installing permanent security.
CN13	150BD	170FA	
Pr (mccm)	14EFE	16EFE	
&EET		11300	

Note: &EET is taken from the last page of the SYSGEN listing, from the segment named &EET and not the TASK &EET!!! This value may vary depending on what the user has sysgennd.

MICROSYSTEMS PRODUCT  
FIELD BULLETIN  
\*\*\*CONFIDENTIAL\*\*\*

Date: September 14, 1982

MPFB 0017

Product Type: VERSAdos 3.0 MCCM FIRMWARE

Contributed By: MM

Contact: Software Specialists  
Field Engineering  
Tempe Operations  
(602) 829-3100

Information Type:  As Needed  
 Mandatory  
 Information Only

\*\*\*\*\*  
Symptom / Problem                      VERSADOS 3.0 MCCM 'FEATURES'

VERSAdos 3.0 MCCM firmware has many "new" and customarily "undocumented" features. These are:

1. The firmware strips out nulls, #00, even in image mode. (SPR 360)
2. The firmware considers \$DE as an end of message terminator.
3. The firmware considers \$8D as an end of message terminator from a TTY device.
4. The firmware inhibits the ASCII FILE TRANSFER program from working correctly MCM-MCM, or MCM-HC 3T. (SPR 425)
5. If you output exactly 80 characters to an MCM port, NO <cr><lf> is sent at the end of the line, even if the port was sysgened for a line length of 132 characters. (SPR 320).
6. Console I/O of a data block greater than 32766 bytes will result in only the first character being sent out. (SPR 394).

\*\*\*\*\*  
Solution / Fix

If a customer has to transmit binary data through the MCM he may want to get the source and modify it, or transmit everything in S-record format to avoid getting one of these early terminators.

MICROSYSTEMS PRODUCT  
FIELD BULLETIN  
**\*\*\*CONFIDENTIAL\*\*\***

Date: October 15, 1982

MPFB 0018

Product Type: VERSAdos 3.0 & Modems

Contributed By: MQ & MM

Contact: Software Specialists  
 Field Engineering  
 Tempe Operations  
 (602) 829-3100

Information Type:  As Needed  
 Mandatory  
 Information Only

\*\*\*\*\*  
 Symptom / Problem                      CHANGE MCCM PORT FOR MODEM HOOK UP

Many customers would like to add a modem to their EXORmacs with VERSAdos 3.0. The following procedure may prove helpful.

\*\*\*\*\*  
 Solution / Fix

1. Use the current version of the MCCM card.
2. Move the appropriate jumpers on the MCCM card to the modem position:, i.e. block K7 for CN11 or CN21, block K8 for CN10 or CN20, block K9 for CN13 or CN23, block K10 for CN12 or CN22.
3. Some software information must now be modified to indicate the existence of the modem on that port and any change in the baud rate for that port. This can be done with a new SYSGEN or patches to VERSADOS.SY.
4. If resysgening: (a) the DCB for the device must be changed from an EXORterm (\$1E) to a non-EXDRterm (\$1F) (see page 5-3 of the sysgen manual M68KSYSGEN/D2). This parameter will have to be changed in the file IDC.SA, /6; (b) the sysgen hardware configuration must be changed to reflect any new baud rate, etc. This is the HWIFCNxx parameter in SYSCMD.SA and is described on page 5-6 of the Sysgen manual. For example, for a 300 baud modem the configuration information would be \$84050350.

NOTE: You do not set the bits up for modem, VDOS talks to the modem as if it was a non-EXORterm terminal, the modem does the rest.

5. If patching VERSADOS.SY for the STANDARD 3.0 MULTI-HARD sysgen:
 

for CN10	for CN11	for CN12	for CN13
= PATCH VERSADOS.SY			
> 0 16200			
> D3A	DB8	E36	EB4
1F	1F	1F	1F (was 1E)
.	.	.	.
> D80	DFE	E7C	EFA
84050350	(Whatever you need for the hardware configuration information, see item (4) )		

6. Offsets into the control block via eyeballing:
 

offset	contents	comments
0	CNxx	Name of port in ASCII
\$20	1E	change to 1F, see item (4)
\$66	00000000	change to hardware config info



MICROSYSTEMS PRODUCT  
FIELD BULLETIN  
\*\*\*CONFIDENTIAL\*\*\*

Date: August 1, 1983

MPFB 0020

Product Type: MCCM General Information

Contributed By: MM

Contact: Software Specialists  
Field Engineering  
Tempe Operations  
(602) 829-3100

Information Type:  As Needed  
 Mandatory  
 Information Only

\*\*\*\*\*

Information

07.14.83mlm

MCCM General Information & Errata

When the MCCM receives a character, the character is first placed into a five character queue. If another character is placed into this queue before the first one was removed, then CTS (Clear to Send, RS-232 pin 5) is "dropped" (logical zero) to tell the sender to wait momentarily. This occurs only if the I/O request was an Image Read, Formatted Reads will allow the character to be overwritten. If the sender does not wait, characters are continued to be saved into the five character queue. Another task in the MCCM looks at the character queue. Another task in the MCCM looks at the character queue and pulls the characters out of it and into a 256 byte queue. When the 256 byte queue is about half full, or the end of the line is encountered (\$0D, \$8D, \$DE), the MCCM does DMA to the 68000 memory. Note that all nulls (\$00) are stripped as they are received by the MCCM.

If the user is doing "Image Read/No Echo" (Image mode), no character is echoed, except it appears, that a carriage return echoes a line feed - carriage return (SPR 677). A major advantage to Image mode reads is that the MCCM will buffer up characters between Image Read requests if the requests are made before the 5 byte buffer is full. In Formatted Reads, all characters between the completion of one I/O request and the next I/O request are lost. Using Image mode reads reduces the possibility of data loss; this feature was originally developed to work with the Data I/O PROM Programmer software, PP1.

The MCCM does not have a 'real' X-ON/X-OFF feature. If it receives a control-W it will continue sending characters until the end of the current record. Most X-ON/X-OFF features allow you to pause within a record, but the MCCM was designed for record oriented I/O and does not presently have this capability. But, if the 2661's CTS line drops, RS-232 DTR (Data Terminal Ready), the 2661 will stop transmitting when its shift register is empty. Thus the MCCM will stop transmitting after the current or next character has been transmitted.

If you output exactly 80 characters to an MCCM port, no line feed - carriage return is sent at the end of the line, even if the port was sysgened for a 132 byte line. This can cause problems for those users with serial printers (SPR 320).



When inputting records greater than 255 bytes in Format mode, the I/O request will terminate on the 255th character and a "EA" error, DATA OVERRUN, is returned to the requester (SPR 799). Inputting in Image mode is also limited to 255 bytes per record. (For example, enter "=COPY #,FILE", and type in 255 characters). The I/O request for input will hang on the 248th character if the terminal you request to do I/O from is not your default logon terminal.

Whenever you receive a VERSAdos IOS error code of "E8", CHECKSUM ERROR, the communications chip actually has encountered a framing error during data transmission.

If the user is doing Formatted Reads (Pascal, COPY command, etc.) each character is echoed, except that a carriage return echoes a line feed - carriage return. This is true unless the sender begins sending data as soon as the line feed character is received. In this case, the MCCM will echo a carriage return with the next record but no line feed (SPR 798 says a 0.157 second delay between receiving the line feed and sending the next block of characters will correct this, unverified SPR).

The MCCM can not keep up with full 9600 baud on all four serial ports. But revision 1.08 of the MCCM firmware will allow ONE of the serial ports to keep up with a full 9600 baud line if there is NO activity on any other MCCM port (including the printer port). The common error from trying to do full 9600 baud communication, and the MCCM not being able to keep up with it, is a DATA OVERRUN ERROR.

MICROSYSTEMS PRODUCT  
FIELD BULLETIN  
 \*\*\*CONFIDENTIAL\*\*\*

Date: August 1, 1983

MPFB 0021

Product Type: EXORmacs software (IPL)

Contributed By: MM

Contact: Software Specialists  
 Field Engineering  
 Tempe Operations  
 (602) 829-3100

Information Type:      As Needed  
     Mandatory  
  x   Information Only

\*\*\*\*\*

Information

03.22.83mlm

RESETTING SECTOR 0 TO GET IT TO POINT TO IPL.SY

1. Do a directory of IPL.SY to locate where it is on the disk:

```
=DIR 0.&IPL.SY;A
DIR VERSION 111781 3    3/22/83    15:20:20
SYS:0000..IPL.SY
```

START	END	LOG EOF	# OF RECORDS	WC	RC	FT	REC LEN	KEY LEN	FAB LEN	DB LEN	DATE CHANGED	DATE ACCESSED
\$42AC	\$42CD	-	-	PP	PP	C	-	-	-	-	3/2/83	3/7/83
SIZE	34/\$22											

TOTAL SIZE 34/\$22  
 NUMBER FILES RETRIEVED = 1

2. Locate the start field and the total number of sectors for this version of IPL.SY. In the example above IPL.SY starts at \$42AC and is \$22 sectors long.

3. Do an interactive DUMP on the volume to change sector 0 of the disk. You may have to terminate the spooler and any printer tasks before you can have access to the volume.

```
=DUMP #HDOO;I
>R 0          {Read sector zero into the change buffer}
>M 16        {Begin changing at offset $16 in the change buffer}
00 '.'?42<cr> {Change the Physical Sector Number to the one found in}
00 '.'?AD<cr> {Step 2 PLUS ONE, bypassing Loader Info Block}
00 '.'?<cr>   {Skip the next byte}
00 '.'?21<cr> {Enter the length of IPL.SY, found in step 2, MINUS 1}
>D          {Display the changes}
```

```
SN=$0
00 53 59 53 20 00 00 00 00 00 01 00 81 00 00 00 8A  SYS .....
10 00 00 00 00 00 00 42 AD 00 21 00 00 00 00 00 00  .....B..!.....
20 00 00 00 00 03 ED 20 20 20 20 20 20 20 20 20 20  .....
30 20 20 20 20 20 20 20 20 20 20 30 33 30 30 F4 F7  ..... 0300..
40 0F 1E 2D 3C 4B 5A 69 78 87 96 A5 B4 C3 D2 E1 F0  ..-<Kzix.....
50 0F 1E 2D 3C 4B 5A 69 78 87 96 A5 B4 C3 D2 E1 F0  ..-<Kzix.....
60 F1 F2 F4 F8 F9 FA FC FE FF 7F BF DF EF 6F AF CF  .....O..
70 4F 8F 0F 07 0B 0D 0E 06 0A 0C 04 08 04 02 01 00  0.....
80 00 00 00 00 00 00 00 00 00 00 00 00 00 82 00 08  .....
90 00 00 00 00 00 00 00 00 00 00 00 00 00 00 00 00  .....
A0 00 00 00 00 00 00 00 00 00 00 00 00 00 00 00 00  .....
B0 00 00 00 00 00 00 00 00 00 00 00 00 00 00 00 00  .....
C0 00 00 00 00 00 00 00 00 00 00 00 00 00 00 00 00  .....
D0 00 00 00 00 00 00 00 00 00 00 00 00 00 00 00 00  .....
E0 00 00 00 00 00 00 00 00 00 00 00 00 00 00 00 00  .....
F0 00 00 00 00 00 00 00 00 45 58 4F 52 4D 41 43 53  .....EXORMACS
```

```
>W 0          {Write sector 0 back out to the disk}
>Q          {Quite DUMP and try to boot up}
```

4. If IPL.SY's starting Physical Sector Number, \$42AC in the example above, is too large to fit in a word value, then place it into a longword value starting at offset \$41 in sector 0. If IPL.SY's length should ever be larger than one byte, then use the word starting at offset \$18. (The example above is using only part of the actual fields.)
5. For more information see the VERSADOS Facilities Manual under the REPAIR utility.

MICROSYSTEMS PRODUCT  
 FIELD BULLETIN  
 \*\*\*CONFIDENTIAL\*\*\*

Date: August 1, 1983

MPFB 0022

Product Type: EXORmacs software (CRASHANAL)

Contributed By: MM

Contact: Software Specialists  
 Field Engineering  
 Tempe Operations  
 (602) 829-3100

Information Type:  As Needed  
 Mandatory  
 Information Only

\*\*\*\*\*

Information

05.27.83mlm

ANALYZING A CRASHED VERSAdos ON VMC OR EXORmacs

If an EXORmacs based VERSAdos system crashes, the code 'AF' will appear in the EXORmacs indicator lights. If a VMC 68/2 system crashes, the system will simply hang up. In either case VERSAdos may have saved the cause of the crash in memory before going down. This information can be useful in isolating hardware or software problems, especially with sites that have regular crashes.

The following notes are meant to provide additional information to the Crash Analysis procedure found in "M68000 REAL-TIME MULTITASKING SOFTWARE USER'S GUIDE", M68KRMS68K, appendix I. The description found in the user's guide is useful but lacks niceties such as the addresses of the mentioned routines for standard configurations.

The following table assumes the site is using the "standard" RMS68K that was released within the noted VERSAdos version.

	VERSAdos 3.0 EXORmacs	VERSAdos 4.1 EXORmacs	VMC 68/2	VERSAdos 4.2 & 4.21 EXORmacs	VMC 68/2
CRASHSAV	\$600	\$400	\$800	\$400	\$800
EXCEPT	\$14E6 to \$1815	\$14E6 to \$1815	\$1798 to \$1AC7	\$14E2 \$1811	\$181E to \$1B4D
TERM	\$35D6 to \$38BF	\$380E \$3B0D	\$3AB8 to \$3DB7	\$380A to \$3B1F	\$3B3E to \$3E53
PROGINT 2	\$154A	\$154A	\$17FC	\$1546	\$1882
PROGINT 3	\$154C	\$154C	\$17FE	\$1546	\$1884
PROGINT 4	\$154E	\$154E	\$1800	\$154A	\$1886
PROGINT 5	\$1550	\$1550	\$1802	\$154C	\$1888
PROGINT 6	\$1552	\$1552	\$1804	\$154E	\$188A
PROGINT 7	\$1554	\$1554	\$1806	\$1550	\$188C
PROGINT 8	\$1556	\$1556	\$1808	\$1552	\$188E
PROGINT 9	\$1560	\$1560	\$1812	\$155C	\$1898
PROGINT A	\$1558	\$1558	\$180A	\$1554	\$1890
PROGINT B	\$1554	\$155A	\$180C	\$1556	\$1892
COMINT	\$12FC to \$14B3	\$136E to \$14B3	\$1620 to \$1765	\$136A to \$14AF	\$1640 to \$1785

If you appear to get an exception in supervisor state (step 3) of M68KRM68K, appendix I) subtract 2 from PC2 before looking in the PROGINT table for the type of exception. For memory problems the address field, ADDR, will isolate the board with the apparent problem.

An alternative to analyzing a crash directly on the crashed machine is to get a memory dump and use the DUMPANAL facility later. To get a memory dump refer to the BD command of MACSbug and VMCbug. To use DUMPANAL refer to the "VERSADOS System Facilities Reference Manual", M68KVSF.

MICROSYSTEMS PRODUCT  
FIELD BULLETIN  
\*\*\*CONFIDENTIAL\*\*\*

Date: August 1, 1983  
Product Type: SYMBUG/A 2.00  
Contact: Software Specialists  
Field Engineering  
Tempe Operations  
(602) 829-3100

MPFB 0023  
Contributed By: MM  
Information Type: \_\_\_ As Needed  
                  \_\_\_ Mandatory  
                  \_x Information Only

\*\*\*\*\*

Information

05.27.83mlm

KNOWN BUGS/CAUTIONS WITH SYMBUG/A 2.00

1. Usage of the TASK command causes the task note level to be changed unpredictably regardless of the note level specified in the command (if any). The note level is usually changed to a value that cannot be displayed with the STAT command. The result of this bug is that set breakpoints may not be enabled at execution time.

(#282)

The following patch corrects this problem:

```
=PATCH SYMBUG
M 44AA;DI
  CMP.B #1,DO      (WAS BSR.L $003E94 )
  BEQ.S #+6        (WAS CMP.B #1,DO   )
  MOVE.W D2,28(A4) (WAS BEQ.S $0044DE )
  BSR $3E94        (WAS MOVE.W D2,28(A4)
```

Q

2. Binary and decimal display options do not work. (#307)
3. Relinking a program that had a "DB" file does not change the status of the "db" file if "-D" is specified. SYMBUG does not check revision information between the "DB" and "LO" files. Thus the user could reassemble and re link and end up with mismatching "DB" and "LO" files. (#334)
4. When SYMBUG aborts with a 'MAP FULL ERROR' a second abort message is given when the next command is entered. (#335)
5. SYMBUG may abort with a 'MAP FULL ERROR' when invoked because it does not have enough space allocated to hold the symbol table. This is especially true with programs utilizing large library routines such as PASCALIB.RO.

To allocate more symbol table space follow the example below:

```
=SYMBUG (#526)
MAXIMUM TASK COUNT (1 -> 19)? 19
SYMBUG ? LOAD TAS
SYMBUG ? ATTA TAS
SYMBUG TASK? .....proceed as you normally would.....
```

If the maximum task count of 19 is not enough to eliminate the MAP FULL error the following patch may be applied to SYMBUG/A 2.0 to allow symbol table space for up to 99 tasks (be input to the MAXIMUM TASK COUNT question above).

```
=PATCH SYMBUG.LO
mm 4D7
39          (Was 31, change maximum task count message)
.
MM 538
31          (Was 30, change to revision 2.01)
.
MM 3BOE
E9          (Was E3, used to allocate more table space)
.
MM 3AF1
63          (Was 13, change maximum task count parameter)
.
Q
```

6. The disassembler cannot distinguish between symbolic operands and numeric operands, nor can it determine the difference between symbols of the same value. (#367)
7. SYMBUG disassembles BRA.S instructions as BT.S. (#368)
8. SYMBUG disassembles both ADD.B Dn/Dm and ADD.L Dn/Dm as ADD Dn, Dm. (#401)
9. SYMBUG's assembler will justify ASCII characters to the left-most byte. The Resident Assembler justifies ASCII characters to a word boundary if it is one or two characters, or to a long word boundary if the string contains more than two characters. (#413)
10. SYMBUG generates incorrect addresses for symbols defined by 'EQU #' in the second of two modules linked into the same section. The address generated is the correct offset but its base is the section base and not the module base. (#429)
11. The first time SYMBUG is invoked on a file all symbolic references are correct. If SYMBUG is invoked again on the same file during the same session, any symbolic references may be off by one byte.
 

First Time:	Second Time:	(#438)
CLR.W DOG	CLR.W DOG+1	
12. SYMBUG can't find the symbol file if it has been renamed (i.e., =RENAME <old-name>.\*,<new-name>.\* ). (#458)
13. SYMBUG will "lose" the symbols in the first module of a multi-module load module when invoked successively with the same number specified for TASK COUNT. (#459)
14. If a BREAK is entered when SYMBUG is waiting for a response to "MAXIMUM TASK COUNT", the only way to exit the "WHAT?" question is to terminate the task from another terminal or power down the system. (#482)

15. The STAT command causes any registers changed to revert to their previous values. The following sequence shows this problem (#499)

```
DF
MS .A7 2800
STAT
DF      {A7 will have its previous value again}
```

16. SYMBUG's assembler does not correctly assemble CMPI.8 #\$OD,1(A1).(#508)

17. The DE ECHO command does not work for MCCM printer devices. (#525)  
(#533)

To copy SYMBUG information to an MCCM printer, first output the data to a disk file and then COPY or LIST it to the line printer. When outputting to a disk file the following sequence should be observed:

```
DE #FN
DE FILE <file-name>      {The file must ALREADY exist and }
                          {the extension MUST be specified. }
DE ECHO                   {Everything will be echoed to the file.}
```

18. Pascal programs in SYMBUG do not terminate normally, they terminate on a TRAP #14 before executing a TRAP #1. To better handle Pascal programs set the exception mask as follows: (#527)

```
MS .SM 01FFBFE1
```

19. SYMBUG, and the task being debugged under SYMBUG, may both compete for access to the user's interactive device. When SYMBUG issues a prompt, and the user's task is also requesting input, the user must enter something (carriage return, go, etc.) so SYMBUG's ID request will complete and allow the user task's request to be processed. (#625)

20. SYMBUG will abort with an 8010 error if the user enters into the one line assembler either: 1) an instruction using a hexadecimal number but leaving off the \$, (i.e., MOVE.L #FFF,DO), or 2) an instruction referencing a label in another module specified without the module name (i.e., JMP BB where BB is in a separately assembled module). (#625)

21. SYMBUG's disassembler disassembles \$B290 as CMP (A0),D1 when you should get  
CMP.L (A0),D1. (#676)

22. When tracing, using the T instruction to trace each instruction, the instruction following any TRAP instruction is not displayed. If a TRAP instruction is traced using the T <count> command where <count> is greater than 7, the EXORMacs enters MACSbug. Typing 'G' on port #CNOO returns to VERSAdos. (#686)

23. If the MM command is used in disassembly mode to patch a MOVEM instruction subsequent output of the DF and MD commands is corrupted. (#687)

24. When using SYMBUG in for multitasking environment and a breakpoint is set in a foreground task, then the task stops but the breakpoint is not displayed. The breakpoint will be displayed if the task in which the breakpoint occurs is not the foreground task. (#689)

25. If the name of a task is different from the first four characters of the load module, then the task is loaded by SYMBUG but its "DB" file is not found. (#689)



26. If in the course of debugging a task the user lets the task run free, GO, and then stops it periodically, STOP <task-name> or the BREAK key, SYMBUG will eventually abort with a MAP FULL ERROR. (#771)  
(#737)
27. The NOPAGE option has no effect on SYMBUG. (#750)
28. None of the SYMBUG error messages are documented. (#374)

MICROSYSTEMS PRODUCT

FIELD BULLETIN

\*\*\*CONFIDENTIAL\*\*\*

Date: August 8, 1983  
Product Type: SYMBUG/A 2.00  
Contact: Software Specialists  
Field Engineering  
Tempe Operations  
(602) 829-3100

MPFB 0024  
Contributed By: SK  
Information Type:   x As Needed  
       Mandatory  
       Information Only

\*\*\*\*\*

VDS 4.1, 4.2, 4.21 MCCM DEVICE CONTROL BLK

This information applies to VERSAdos 4.1, 4.2 and 4.2.1 MCCM ports. The information does NOT apply to the debug ports NOR does it apply to VERSAdos 3.0 or earlier.

The following is a procedure to modify the MCCM port parameters without having to execute a SYSGEN. This procedure does not apply to configuration changes to increase the number of ports available nor to increase the size of any of the queues or tables existing for VERSAdcs. Note that <c/r> = carriage return.

1. Locate the software/hardware configuration word to be changed for a particular port in the file VERSADOS.SY. The easiest way to do this is:

Scan VERSAdos by entering SYSANAL and using the Memory Display command (MD) to dump memory to the screen. For example, type:

```
=SYSANAL
```

```
>MD 16000 4000
```

This will dump VERSAdos from \$16000 to \$1A000. The user should look on the right-hand "ASCII--column" for the mnemonic of the port that is to be changed. For example (CN12). When it appears on the screen a <ctrl-W> is entered to temporarily stop the display. The address of the beginning of the mnemonic is recorded. That is, the address of the C in CN12 is recorded and used as the base for calculations into the Device Control Block for that port. After the base address has been recorded, hit the break key to get back to the command line in SYSANAL and type QUIT<cr> to exit SYSANAL.

2. The operating system VERSAdos is just the execution of a very elaborate program named VERSADOS.SY. So to change the operating system, we must make modifications to this program. Having determined the base address of the port to be modified, the PATCH utility can be used to modify the port. Before patching VERSADOS.SY, be sure to copy the file over onto another file, that is, type COPY VERSADOS.SY,SAVE.VERSADOS.SY;B. To determine the location to PATCH, add the start of the ports DCB (the address of C that was determined above) to the offsets defined below.

For example, if we wanted to change the Baud rate of CN12 from 9600 to 300, and assuming the vanilla base address of \$16BDA. First we find that the Baud rate information is located at offset \$8A in the DCB, from the offset table below. We add \$16BDA + \$8A = \$16C64. This is the address of the Baud rate information. Next we find the value that represents 300 Baud, from the Baud rate table below, and note that 300 Baud = \$05. To Patch the Baud rate we type

```
=PATCH VERSADOS.SY<c/r>
```

```
>M $16C64<cr>
```

```
>$16C64 OE '.' 05<c/r>
```

```
>$16C66 00 '.' .<c/r>
```

```
>QUIT
```

- Once VERSADOS.SY has been modified and written back to the disk, the system must be rebooted for the changes to take effect.

VERSADOS 4.1 and 4.2 MCCM CRTDCB (sample CRTDCB for CNxx)

```

016856 016835 0001 68EE 434E 3131 0000 0000 2E49 4F53 ..h.CN11.....IOS
016866 016866 0000 0001 0000 0000 0133 0000 0000 0000 .....3.....
016876 016876 0000 1E01 434F 4D31 0100 0000 0000 0002 .....COM1.....
016886 016886 0004 E016 0000 0000 0000 0001 4F18 0001 .....0...
016896 016896 4F56 0000 0000 0000 0000 0001 4ED8 0000 OV.....N...
0168A6 0168A6 0000 0000 0000 0C00 0000 0000 0000 0000 .....
0168B6 0168B6 0000 0000 0000 0000 8011 0320 047C 5803 ..... ..X.
0168C6 0168C6 0000 0050 0000 0018 000D BBA0 000D BBA0 ...P.....
0168D6 0168D6 1700 030F 1318 0DDE 0000 0DOA 0C00 0E00 .....
0168E6 0168E6 0000 0000 0000 0000 0001 6986 434E 3132 .....i.CN12
    
```

```

**MCCM**
OFFSETS FROM 'C' IN CNxx (in bytes)
-----
-$ 4 4 Address of next DCB in linked list
$ 0 4 ASCII identification of this DCB (CNxx)
$ 4 4 Address of DCQ entry
$ 8 4 Name of task making the request
$ C 4 Session of task making the request
$ 10 4 Address of Logical Unit Table
$ 14 2 Device attributes (see Device Attributes Table)
$ 16 2 Write/Read protect codes
$ 18 2 'Device in use' flag
$ 1A 4 Write/Read counts
$ 1E 1 Device flag (device code) (see Device Code Table)
$ 1F 1 Device flag (device status) (see Device Status Table)
$ 20 4 Channel identification (see Channel Identification Table)
$ 24 1 Device number associated with the channel
$ 25 1 Task priority
$ 26 4 Current record number
$ 2A 23 Storage area for the IOCB being processed
$ 46 4 Logical address of IOCB in user's address space
$ 4A 1 Configuration coordination flag (0 --> at defaults)
$ 4B 1 Break count
$ 4C 1 Address of break service Logical Unit Table
$ 50 4 Break service address
$ 54 4 Device Buffer Zone
$ 58 4 Device Buffer Zone
$ 5C 4 Device Buffer Zone
$ 60 4 Device Buffer Zone
$ 64 1 Space for status fields
$ 65 1 Space for status fields
$ 66 1 Space for status fields
$ 67 1 Space for status fields
$ 68 2 Attributes mask (mask is ANDed with Attributes word)
$ 6A 2 Parameter mask
$ 6C 2 Attributes word (see MCCM Terminal Attributes Word)
$ 6E 2 Number of characters per line (80 [$50] default)
$ 70 4 Number of lines per page (24 [$18] default)
$ 74 4 Write timeout (0 --> no timeout)
$ 78 4 Read timeout (0 --> no timeout)
    
```

```

*****
#4,2 A*VANILLA ADDRESSES *
* #CN10 $16AA2 *
* #CN11 $16B3A *
* #CN12 $16BD2 *
* #CN13 $16c6A *
*****
    
```

\$ 7C 1 XOFF character (\$17 default --> Control W)  
 \$ 7D 1 XON character (\$00 default --> any character)  
 \$ 7E 1 Break equivalent character (\$03 default --> Control C, not app in MACs)  
 \$ 7F 1 Discard output character (\$0F default --> Control O)  
 \$ 80 1 Reprint line character (\$13 default --> Control S)  
 \$ 81 1 Cancel line character (\$18 default --> Control X)  
 \$ 82 4 Read terminator (\$0DDE0000 default)  
 \$ 86 4 End-of-Line string (\$0D0A0000 default)  
 \$ 8A 1 Baud rate code (\$0E = 9600 Baud) See Baud Rate Table  
 \$ 8B 1 Null padding  
 \$ 8C 1 Terminator class  
 \$ 8D 1 Terminal type (0 = EXORterm 155, non-zero = anything else)  
 \$ 8E,8F,90,91,92,93 Reserved

## CHANNEL IDENTIFICATION TABLE

Value	Channel Type
1	ACIA Device
2	PIA A-Side Device
3	PIA B-Side Device
4	CRTC Device
5	SSDA Device
6	ADCC Device
\$10	Disk IPC
\$11	MCCM IPC
\$20	SASI on I/O Channel
\$22	Winchester on I/O Channel
\$22	Floppy on I/O Channel
	Printer Ports \$50-\$5F
\$50	EXORmacs PIA
\$51	VM01 Parallel
\$52	RTTLIO Parallel
	Serial Ports \$60-\$6F
\$60	7201 A-Side on VM02
\$61	7201 B-Side on VM02
\$62	7201 A-Side on VM80
\$63	7201 B-Side on VM80
\$64	7201 A-Side on RSIO
\$65	7201 B-Side on RSIO

## DEVICE ATTRIBUTES TABLE

Bit	Attribute
0	Support Read
1	Supports Write
2	Support Binary
3	Support Random
4	Supports Image
5	Supports Halt I/O
6	Supports Position Record
7	Supports File Mark
8	Interactive Device
9	Printer Device
10	Supports Spooling
11	Supports write with CRC Check
12-15	Reserved

## BAUD RATE TABLE

Value	Meaning	Value	Meaning	Value	Meaning	Value	Meaning
\$00	50 Baud	\$04	150 Baud	\$08	1800 Baud	\$0C	4800 Baud
\$01	75 Baud	\$05	300 Baud	\$09	2000 Baud	\$0D	7200 Baud
\$02	110 Baud	\$06	600 Baud	\$0A	2400 Baud	\$0E	9600 Baud
\$03	134.5 Baud	\$07	1200 Baud	\$0B	3600 Baud	\$0F	19200 Baud

## DEVICE CODE TABLE

<u>Decimal</u>	<u>Hex</u>	<u>Meaning</u>
30	\$1E	EXORterm 155 terminal on MCCM
31	\$1F	Modem or non-EXORterm terminal on MCCM
35	\$23	EXORterm 155 on local Driver
36	\$24	Modem or non-EXORterm terminal on local driver
40	\$28	Hard disk - fixed platter (64 sectors/track)
41	\$29	Hard disk - removeable platter (64 sectors/track)
50	\$32	Floppy disk - single sided - single density
51	\$33	Floppy disk - double sided - single density
55	\$37	Floppy disk - double sided - single density
90	\$5A	Low speed line printer on MCCM
91	\$5B	High speed line printer on MCCM
95	\$5F	Low speed line printer on local driver

## DEVICE STATUS TABLE

<u>Bit</u>	<u>Attribute</u>
0	0 - Device offline 1 - Device online
1	0 - Device not write protected 1 - Device write protected
2	1 - Device status has changed
3	1 - Device busy for initialization
4	1 - Device busy for configuration
5	0 - No timer to be cancelled for this device 1 - Timer to be cancelled for this device
6	1 - Ignore timer event for this device
7	Reserved

MCCM TERMINAL ATTRIBUTES WORD (TCP\$ATW) FOR VERSADOS 4.1 & 4.2 used in &EET  
 (default \$0180) (TERMINAL ATTRIBUTES MASK default \$0470)  
 (\* indicates default mask allows parameter)

BIT	0	TCP\$CPY	1 means the terminal is a hardcopy device, not a CRT
	1	TCP\$XCTL	1 means use XON/OFF to control terminal's transmission, not CTS
	*2	TCP\$BITS	1 means transmit and receive 7 bits/char rather than 8
	*3	TCP\$STPB	1 means follow each char sent with 2 stop bits rather than 1
	*4	TCP\$USEP	1 means parity should be checked and generated
	*5	TCP\$PRTY	1 means parity (if used) should be even rather than odd
	*6	TCP\$ECHO	1 means the driver should not echo characters
	7	TCP\$TAHD	1 means the type-ahead feature should not be used
	8	TCP\$IFUL	1 means filling the buffer on a read should terminate the read
	9	TCP\$PNUL	1 means NUL char's should be considered data for image reads
	*10	TCP\$MODM	1 means the port is connected to a modem
	11	TCP\$OFFH	
	12-15	RESERVED	

DEBUG TERMINAL ATTRIBUTES MUST BE SET TO \$9500. THE \$9500 IS USED TO SET THE CONTROL REGISTER IN THE ACIA ON THE DEBUG CARD FOR .TTY.

MICROSYSTEMS PRODUCT  
FIELD BULLETIN  
\*\*\*CONFIDENTIAL\*\*\*

Date: September 28, 1983

MPFB 0025

Product Type: 68K LINKER 1.4 - 1.6

Contributed By: MK

Contact: Software Specialists  
Field Engineering  
Tempe Operations  
(602) 829-3100

Information Type:  
\_\_\_ Mandatory  
\_\_\_ As Needed  
 x  Information Only

\*\*\*\*\*

Symptom / Problem                      LINKING A PROGRAM ON A NON-MMU SYSTEM

-----  
As the number of 68000-based products offered by Motorola Microsystems increases, so does the number of programs that users wish to port from one product to another. One of the areas that can cause confusion is porting a program from an MMU-based system to a non-MMU based system or vice versa. Here are some hints on what to do to reduce the number of problems you may experience.

\*\*\*\*\*

Solution / Fix

-----  
On an MMU-based system, such as the EXORmacs or the VME/10, four logical segments are available for use by your program. These segments need not inhabit contiguous memory. The code generated by your assembly language or high-level language program need not be position independent. The linker is used to group like sections together, for example:

```
=LINK ,,TEST
SEG CODE(R):8-14      /*read-write code segment*/
SEG DATA:0-7        /*read-write data segment*/
SEG DAT1:15          /*read-write data segment*/
IN TEST              /*input file, given after segment defs*/
END
```

On a non-MMU-based system, such as VME110 or VMC68/2, all logical addresses are taken as physical addresses. In this case either the code must be written as position independent, or the linker must assign physical addresses to the segments. Physical addresses are assigned through use of the segment, SEG, user command even though there is no MMU in the product. The user-specified starting address given in the SEG command is interpreted as a physical address instead of a logical address. For example:

```
=LINK ,,TEST;S      /*S option*/
SEG CODE:8-14 $10000 /*segment starting address*/
SEG DATA:0-7,15
IN TEST
END
```

could be used for linking most programs that are not position independent. The S option will allocate the segments contiguously. The first segment will be loaded at \$10000 in physical memory with the second segment immediately following the first. NOTE: If no physical address was given the linker would default the start address to zero (0), and it would also assume that the resulting module would be position independent!

The linker can also be used to set up memory at different locations. For example, in an assembly language program, the code segment is to start at \$1000 and the data segment is in four parts. Section 0 is to start \$10000, section 1 at \$12000, section 2 and \$14000 and section 3 at \$16000. Sections 4-7 and 15 are not used. This can be done as follows:

```
=LINK ,,TEST;S
SEG PROG(R):8-14 $1000
SEG DATA:0-3 $10000
SEG EMPT;4-7,15          /*these sections not used*/
START 1 $12000
START 2 $14000
START 3 $16000
IN TEST
END
```

Note that the S option is specified to assign contiguous memory locations. Note that five absolute addresses were assigned through the use of two SEG and three START user commands. The linker will only allow a total of four SEG user commands to be given per each invocation. The first segment will be loaded at absolute \$1000 in memory. The second segment will be loaded at \$10000 in memory. Within the second segment section 3 will be loaded at \$16000 in memory, section 2 at \$14000 in memory, section 1 at \$12000 in memory, and section 0 at \$10000.

For further information and examples, refer to the SEG and START user commands in the linker manual, M68KLINK(D6), and Chapter 5 of the Pascal User's Guide, M68KPASC/D6.

MICROSYSTEMS PRODUCT  
FIELD BULLETIN  
\*\*\*CONFIDENTIAL\*\*\*

Date: January 26, 1983

MPFB 0026

Product Type: MVME200 / 201

Contributed By: MK

Contact: Hardware Specialists  
Field Engineering  
Tempe Operations  
(602) 829-3100

Information Type:  
 Mandatory  
 As Needed  
 Information Only

\*\*\*\*\*

Symptom / Problem                      VME 200/201 ADDRESS DECODING PROBLEMS

Boards will not work in the Executive mode due to error in address decoder ROMs in location U75. Bad ROMs are labeled B37, complete part number is 51AW4000B37. Boards that have no label on them are probably all right, they were made in Austin before the product transferred.

\*\*\*\*\*

Solution / Fix

Parts can be programmed to correct the error by changing contents of location \$7E from \$0 to \$F. Bad ROMs were on boards shipped in December, 1982. New boards will have ROM number 51AW4000B42, which has the correct code.



MICROSYSTEMS PRODUCT  
FIELD BULLETIN  
\*\*\*CONFIDENTIAL\*\*\*

Date: April 16, 1982

MPFB 0027

Product Type: EXORciser

Contributed By: CH

Contact: Software Specialists  
Field Engineering  
Tempe Operations  
(602) 829-3100

Information Type:  
 Mandatory  
 As Needed  
 Information Only

\*\*\*\*\*

Symptom / Problem MDOS 2MHZ FORMAT PATCH

User cannot format disk at 2MHZ under MDOS with an EXORDisk III disk controller or an Exordisk II controller. This is for both M6800 and M6809. This appears to only happen at 2MHZ and gives errors E8 and 38.

\*\*\*\*\*

Solution / Fix

To alleviate this problem, you must patch MDOS file= FORMAT.CM version 3.03, to perform retries. The procedure is included in addendum A2 for MDOS Manual M68MDOS3 (D2). For those of you who do not have this addendum, here is the data:

Patch for MDOS09 (6809):

Patch Format.CM

139/7E,23,22  
24F/7E,23,22  
317/7E,23,22  
322/86,05,97,30,BD,E8,78,7E,21,3C  
32C,0A,30,26,F6,7E,20,FB  
Quit

Patch for MDOS (6800):

Patch Format.CM

152/7E,23,60  
28E/7E,23,77  
362/7E/23/6D  
36D/86,05,97,30,BD,E8,78,7E,21,55  
376/7A,00,30,26,F5,7E,20,F4  
Quit

MICROSYSTEMS PRODUCT  
FIELD BULLETIN  
\*\*\*CONFIDENTIAL\*\*\*

Date: April 16, 1982

MPFB 0028

Product Type: EXORciser

Contributed By: CH

Contact: Software Specialists  
Field Engineering  
Tempe Operations  
(602) 829-3100

Information Type:  
 Mandatory  
 As Needed  
 Information Only

\*\*\*\*\*

Symptom / Problem RLOAD for 6809 (3.10 or 3.11)

1. FORTRAN common variables not resolved properly by Rload
2. RLOA gives multiple defined symbol errors in certain instances.

\*\*\*\*\*

Solution / Fix

Use rev. 3.00 RLOAD until 3.20 is available, FORTRAN 3.20 and RASMO9 3.10 cannot be used until 3.20 RLOAD is available. Use prior versions of FORTRAN and RASMO9.

MICROSYSTEMS PRODUCT  
FIELD BULLETIN  
\*\*\*CONFIDENTIAL\*\*\*

Date: April 16, 1982

MPFB 0029

Product Type: EXORciser

Contributed By: CH

Contact: Software Specialists  
Field Engineering  
Tempe Operations  
(602) 829-3100

Information Type:  
\_\_\_ Mandatory  
\_\_\_ As Needed  
\_x\_ Information Only

\*\*\*\*\*

Symptom / Problem                      10 WAYS TO CRASH 6809 WITH TRACE

On the 6809, tracing instructions of more than 15 cycles in the user map will cause the processor to crash. These instructions are:

SWI	PULS	
SWI2	PSHS	:::: With 11 or 12 bytes pushed or pulled to/from the
SW13	PULU	stack.
IRQ	PSHU	
SYNC		
CWAI		

\*\*\*\*\*

Solution / Fix

The problem is that there is only a 32 cycle counter on the Debug board that is used in the switching of the map from User to EXEC for the NMI vector fetch. This counter runs out and the NMI is fetched for the user map. NOTE: Fix would be to set up NMI handler in user map to switch to NMI handler in EXEC map.

MICROSYSTEMS PRODUCT  
FIELD BULLETIN  
\*\*\*CONFIDENTIAL\*\*\*

Date: September 9, 1982

MPFB 0030

Product Type: EXORset 35

Contributed By: AZ

Contact: Hardware Specialists  
Field Engineering  
Tempe Operations  
(602) 829-3100

Information Type:  
 Mandatory  
 As Needed  
 Information Only

\*\*\*\*\*

Symptom / Problem                      EXORSET 35 HIGH TEMPERATURE WARNING

EXORset 35 power supply temperatures

The power supply pass transistors can run exceptionally HOT! Tests show a temperature range from 60 Degrees C (140F) to 76 Degrees C (170F). CAUTION should be used when doing repairs in this area. Do not touch the transistors with arms or hands—burns could result.

\*\*\*\*\*

Solution / Fix

No fix is necessary as this is normal operation, and depending on the load imposed by customer requirements will determine how hot they get. Temperatures mentioned above are with worst case loading conditions.

MICROSYSTEMS PRODUCT  
FIELD BULLETIN  
\*\*\*CONFIDENTIAL\*\*\*

Date: November 5, 1982

MPFB 0031

Product Type: M68SETDS351

Contributed By: RW

Contact: Hardware Specialists  
Field Engineering  
Tempe Operations  
(602) 829-3100

Information Type:  
 Mandatory  
 As Needed  
 Information Only

\*\*\*\*\*  
Symptom / Problem                      EXORSET 35 MALFUNCTION CORRECTION

For no apparent reason the EXORSET35 may malfunction causing varied indications: System lockup during edit or assembly, drive errors, loss of screen sync, random characters on the screen, or possible keyboard unpredictable, etc.

\*\*\*\*\*  
Solution / Fix

The FS repair depot has found that approximately 75% of the EXORSET35s in repair for this type of problem can be fixed by simple adjustment of either one or both phase lock loop circuits (one on the floppy disk control card, and the other on the main control board of the EXORSET35).

Follow the well-documented instructions in the EXORSETDS35 User's Manual, pages 6-19 and/or 6-15.

MICROSYSTEMS PRODUCT  
FIELD BULLETIN  
\*\*\*CONFIDENTIAL\*\*\*

Date: September 19, 1983

MPFB 0032

Product Type: VME/10 with VME400

Contributed By: MM

Contact: Software Specialists  
Field Engineering  
Tempe Operations  
(602) 829-3100

Information Type:  
 Mandatory  
 As Needed  
 Information Only

\*\*\*\*\*

Symptom / Problem REJUMPER VME400 ON VME/10

When adding a VME400 to the VME/10 you must change the factory installed interrupt level jumpers from level 3 to level 4. Change jumpers on J5 to 4-6, 10-12, and 16-18. VERSAdos is already sysgened for the VME400 as #CN01 and #CN02. (As sysgened only two terminals can be logged on atr once, 9100.VMES10.SYSCMD.SA parameter NOLOGONS is 2.)

\*\*\*\*\*

MICROSYSTEMS PRODUCT  
FIELD BULLETIN  
\*\*\*CONFIDENTIAL\*\*\*

Date: September 28, 1983

MPFB 0033

Product Type: SERSAdos on VM02

Contributed By: MM

Contact: Software Specialists  
Field Engineering  
Tempe Operations  
(602) 829-3100

Information Type:  
\_\_\_\_ Mandatory  
\_x\_ As Needed  
\_\_\_\_ Information Only

\*\*\*\*\*

Symptom / Problem                      PATCH TO ALLOW BREAKPOINTS ON VM02

It is impossible to boot up VERSAdos on VM02 and then hit software abort and be able to use breakpoints. The bug massacres port #1 and well as port #0. (SPR 854)

There is an ugly patch to put on the serial port driver to mess up the VMC/VERSA-bug RAM area to fool it so it doesn't massacre the serial ports on software abort. The patch varies with different versions of the bug and different versions of VERSAdos. The following applies to VMCbug 1.00 and VERSAdos 4.20.

\*\*\*\*\*

Solution / Fix

For VMCbug 1.00 running VERSAdos 4.20, you patch 4 NOPs in the CMPS driver (address calculated by adding the 3rd longword from the beginning of the driver to the address of the beginning of the driver) to a 'MOVE.L #\$F70014,<ea>', where <ea> is the absolute address of serial port 2 on the bug's link map, symbol 'SER2'. In the above case the patch would be:  
address \$6358 from 4E714E714E714E71 to 21FC00F700140660  
NOP NOP NOP NOP                      MOVE.L #\$F70014,\$660

Note also that to set breakpoints you must patch the VERSAdos vector table !VCT and sest vector 4 to 0001. The following is an example:

000010	4E73	4E75	4EB9	0000	0C7E	1256	4354	0000	NsNuN.....!VCT..
000020	136A	0000	0C14	0100	0C14	0200	1546	0400	.j.....F..
000030	154A	0500	154C	0900	155C	0A00	1554	0C00	.j...L.../...T..

Vector 4 begins at address C2E, so in the above example you would change C30 from 154A to 0001. Note that when this is done SYMbug and Debug breadpoints will no longer work, but VMC/VERSA-bug breakpoints will work.

You should use boot halt to boot the patched version of VERSAdos, then set breakpoints, and then GO <address> dto begin program execution.

MICROSYSTEMS PRODUCT  
FIELD BULLETIN  
\*\*\*CONFIDENTIAL\*\*\*

Date: October 13, 1983

MPFB 0034

Product Type: SERSados on VM02

Contributed By: MK

Contact: Software Specialists  
Field Engineering  
Tempe Operations  
(602) 829-3100

Information Type:  
 Mandatory  
 As Needed  
 Information Only

\*\*\*\*\*

Symptom / Problem                      AF CRASH ON VERSADOS AT LOGON

Using a VERSados 4.20 or VERSados 4.21 sysgen to support ;more than one MCCM may result in an operating system that will crash with an 'AF' abort. The abort will occur when the Periodic Activation Table is full.

A possible scenario would be when VERSados is sysgened for 2 MCCMs and the 7th MCCM user tries to log on. The task .IOS uses the Periodic Activation feature of RMS68K to keep track of timeouts on all VERSados I/O ports.

\*\*\*\*\*

Solution / Fix

In the ;9100.EXORMACS.SYSCMD.SA file change the size of the Periodic Activation Table, PAT from 1 to 3 pages. Then resysgen the operating system.



MICROSYSTEMS PRODUCT  
FIELD BULLETIN  
\*\*\*CONFIDENTIAL\*\*\*

Date: October 17, 1983

MPFB 0035

Product Type: VERSAdos on VM02

Contributed By: CH

Contact: Software Specialists  
Field Engineering  
Tempe Operations  
(602) 829-3100

Information Type:  
 Mandatory  
 As Needed  
 Information Only

\*\*\*\*\*

Symptom / Problem                      VERSADOS 4.1 INITIALIZE MEMORY REQUIREMENT

When booting the EXORmacs with the HDS-400 software (VERSAdos 4.1), the new IPL.SY will give a "BD" display in the status lights. This is caused because memory is not initialized and should only happen on power up.

\*\*\*\*\*

Solution / Fix

The solution is to initialize memory from MACSbug. There are two easy ways to do this. The first is with the MACSbug BI command. The second is to use the front panel to run a self test by: Depressing both the RESET and SYSTEM TEST buttons (in that order), then releasing the SYSTEM TEST button and then releasing the RESET button.

MICROSYSTEMS PRODUCT  
FIELD BULLETIN  
\*\*\*CONFIDENTIAL\*\*\*

Date: October 17, 1983

MPFB 0036

Product Type: VMC 68/2

Contributed By: MM/CH

Contact: Software Specialists  
Field Engineering  
Tempe Operations  
(602) 829-3100

Information Type:  
 Mandatory  
 As Needed  
 Information Only

\*\*\*\*\*

Symptom / Problem                      VMC 68/2 PROBLEMS AND SOLUTIONS

\*\*\*Several problems have been identified with the VMC 68/2 \*\*\*  
They are itemized below.

1. When first installing a VMC system you MUST use the 'V' option on INIT to set a disk up for a VMC. If the 'V' option is not used, the resultant disk can not be booted. (The V option will set an IPL start address at \$E00 in the VID that would be \$0 otherwise. ENTER: INIT #HDxx;V).
2. The User may have trouble getting VERSAdos to boot consistantly. This symptom is entering the BO command and nothing happens, even with several attempts. The problem appears to be with the AUTOLOGON feature. Until a permanent solution is found, the temporary fix is to either:  
a) Resysgen with the AUTOLOGON parameter changed from a 1 to a 0, or  
b) Patch VERSADOS.SY and change address \$10601 from \$01 rto \$00.  
NOTE: This fix inhibits the Auto-long feature so a break must be issued in order to get the VERSAdos logon prompt.
3. Trying to run a sysgen will result in an IOS error \$0C, Insufficient system space, when the first link is attempted. To bypass this problem the :9100.VM02.SYSCMD.SA file should be edited so that MAXLU=10, MOFILES=20 and MODIFFIL=20. Then log on to user 9100 and invoke the sysgen with VM02.SYSGEN.CF ,,,#NULL. Once you see that the chain file has invoked the sysgen command, hit break and stop the process. Next enter END to terminate the chain file. Finally, enter the following command line and sysgen should continue with no problems:  
SYSGEN VM02./5,./7.
4. If the system suddenly goes into VMCbug without notice, the problem may be in the Power Fail Monitor. If this happens often, the power fail ribbon cable can be disconnected. It is located by the power supply in the rear of the chassis.
5. The fact that RMS68K source and object files are under user 9999, is not an error, they are supposed to be there.
6. To allow more than one person to be logged on to the system at once, the parameter MOLOGONS in :9100.VM02.SYSCMD.SA must be changed and another SYSGEN be made.

MICROSYSTEMS PRODUCT  
FIELD BULLETIN  
\*\*\*CONFIDENTIAL\*\*\*

Date: October 17, 1983

MPFB 0037

Product Type: Ascii File TRANSFER (2.0)

Contributed By: MM

Contact: Software Specialists  
Field Engineering  
Tempe Operations  
(602) 829-3100

Information Type:  
      Mandatory  
      As Needed  
      Information Only

\*\*\*\*\*

Symptom / Problem                      ASCII FILE TRANSFER (2.00) PROBLEM

The 4.x release of VERSADOS, HDS and VMC 68/2, have an incorrect version of Ascii File TRANSFER. It must be changed in order for ULOAD to work. The source change and patch should be made to TRANSFER (version 2.00).

\*\*\*\*\*

Solution / Fix

In the source change line 1295 from  
SUB.L        #1, A2                      to  
SUB.L        #1, A0                      .

To find the correct line enter  
=E TRANSFER.SA  
F 1295  
C /A2/A0/  
QUIT

In the TRANSFER.LO module the following patch may be used:  
=PATCH TRANSFER.LO  
M 1ABE;DI  
      SUBQ.L    #1,A0  
.  
Q

MICROSYSTEMS PRODUCT  
FIELD BULLETIN  
\*\*\*CONFIDENTIAL\*\*\*

Date: October 17, 1983

MPFB 0038

Product Type: VERSAdos 4.1, 4.2, & 4.21

Contributed By: MM

Contact: Software Specialists  
Field Engineering  
Tempe Operations  
(602) 829-3100

Information Type:  
 Mandatory  
 As Needed  
 Information Only

\*\*\*\*\*

Symptom / Problem                      VERSADOS 4.X CHANGE NAME OF #PR TO #PR1

NOTE:            The VERSAdos 4.1, 4.2 and 4.21 release no longer refers to the  
MCCM printer as #PR. Instead, they revert back to VERSAdos 2.1  
nomenclature. The first MCCM printer port is named #PR1 and the  
DEBUG printer port #PR.

\*\*\*\*\*

Solution / Fix

The can be changed by editing IOC.SA and swapping #PR for #PR1 in the DCB  
for the first MCCM printer and swapping #PR1 for #PR in the DEBUG printer  
DCB.

MICROSYSTEMS PRODUCT  
FIELD BULLETIN  
\*\*\*CONFIDENTIAL\*\*\*

Date: October 17, 1983

MPFB 0039

Product Type: VME/10 VERSAdos 4.25 UPLOADS

Contributed By: MM

Contact: Software Specialists  
Field Engineering  
Tempe Operations  
(602) 829-3100

Information Type:  
\_\_\_ Mandatory  
 x  As Needed  
\_\_\_ Information Only

\*\*\*\*\*  
Symptom / Problem                      VERSADOS 4.25 UPLOADS PROBLEM  
-----

VME/10 VERSAdos 4.25 with a MVME400 board does not appear to make proper use of CIS/RTS. If the records being downloaded to the MVME400 are not padded with nulls information can be lost.

For Example:

Using the VME/10 UPLOADS command through a MVME400 in the VME/10 to a MVME400 port in a VME chassis with a MVME110, will result in the UPLOADS program becoming hung up.

```
EXORterm 155 --- MVME110                  VME/10 [CNSL] --- Console
                  MVME400                  MVME400
```

Boot VME/10 from console

```
From VMEbug enter TM2 and BREAK...log onto VME/10
Invoke uploads...UPLOADS TESTFILE.SA
Hit control-A to return to VMEbug
Enter command to dump memory to [port 2, such as...DU2 0 FFF
When VMEbug prompt returns, enter transparent mode again...TM2
UPLOADS is now in a hung state
```

(To do the download successfully, apply the following port format command before doing the DUMp command.)

\*\*\*\*\*  
Solution / Fix

To solve the above problem the port on the MVME110's MVME400 must be configured for at least \$25 nulls sent after the carriage return. Use the PF2 or PF3 command to change this parameter for the needed port before doing the transfer.

```
VMEbug 2.0 > PF2 <cr>
STOP BITS=44? <cr>
CHAR NULL=00? <cr>
C/R NULL=00? 25<cr>
```

where <cr> is a carriage return

MICROSYSTEMS PRODUCT  
FIELD BULLETIN  
\*\*\*CONFIDENTIAL\*\*\*

Date: October 17, 1983

MPFB 0040

Product Type: VERSAdos 4.2 UP SYSGEN

Contributed By: MM

Contact: Software Specialists  
Field Engineering  
Tempe Operations  
(602) 829-3100

Information Type:  
 Mandatory  
 As Needed  
 Information Only

\*\*\*\*\*

Symptom / Problem                      VERSADOS 4.2 NODEFVOLS = NOLOGNS

-----  
It needs to be documented that the sysgen parameter NODEFVOLS, number of default volumes, must be at least as large as NOLOGNS, the number of log ons. If it is not large enough users trying to log onto the other ports will receive the error message:

    No CHANGE TO VOLUME, USER NUMBER, OR CATALOG

    and will not be able to get logged onto the system.

    This is true of VERSAdos 4.2 and beyond and should be checked if a customer can only log on a portion of his users onto the system.

\*\*\*\*\*

Solution / Fix

    Update the parameter NODEFVOLS to the number of logons plus (at least) 4.

MICROSYSTEMS PRODUCT  
FIELD BULLETIN  
\*\*\*CONFIDENTIAL\*\*\*

Date: October 18, 1983

MPFB 0041

Product Type: VERSAdos 4.21 HDS-400

Contributed By: MM

Contact: Software Specialists  
Field Engineering  
Tempe Operations  
(602) 829-3100

Information Type:  
 Mandatory  
 As Needed  
 Information Only

\*\*\*\*\*  
Symptom / Problem                      ADDING MULTI-DROP HDS-400's on vdos 4.21  
-----

The new release of HDS-400 software/firmware supports multi-drop operation, but several things need to be done in software to incorporate this enhancement.

\*\*\*\*\*  
Solution / Fix

1. VERSAdos 4.21 must be sysgened for the number of HDS-400 multi-drop lines required. To do this: a) log on to 9100; b) edit the file 9100.EXORMACS.SYSCMD.SA; c) change the sysgen parameter NOTNT to the number of multi-drop lines needed; d) quit the editor; e) run a sysgen for the multi-drop requirement by entering EXORMACS.SYSGEN.CF ,,MULTI-HARD,#NULL f) log off of 9100; g) log on to 0; h) save the old version of VERSAdos by entering RENAME VERSADOS.SY,VDOS.SY ; i) copy down the new version COPY 9100..VERSALOS.SY,0..;B ; j) make change (2) below and k) reboot the system to see if it works.
  
2. Some of the HDS-400 software also needs to be patched for multi-drop operation. To do these patches log on to user 0 and enter MULTIHDS.CF <arg> where <arg> is the number of multi-drop lines (1, 2, 3 or 4). When the chain file is done all necessary patches will have been applied.

MICROSYSTEMS PRODUCT  
FIELD BULLETIN  
\*\*\* CONFIDENTIAL \*\*\*

Date: October 19, 1983

MPFB 0042

Product Type: VERSAdos 4.1 and 4.2

Contributed By: MK

Contact: Software Specialists  
Field Engineering  
Tempe Operations  
(602) 829-3100

Information Type:  
 Mandatory  
 As Needed  
 Information Only

\*\*\*\*\*

Symptom / Problem                      SPOOLER PATCH FOR VERSADOS 4.1 & 4.2

The following patch eliminates the banner in the spooler. It should be useful for those customers wanting to cut down on the amount of paper being produced by VERSAdos releases 4.1 and 4.2

\*\*\*\*\*

Solution / Fix

```
=PATCH SPL.LO
1B80
4E75                      (WAS 41EC)
.
1DE0
42804E75                  (WAS 082C0005)
.
Q
=END
```



MICROSYSTEMS PRODUCT  
FIELD BULLETIN  
\*\*\*CONFIDENTIAL\*\*\*

Date: October 19, 1983

MPFB 0043

Product Type: Data I/O Interface on  
EXORMACS (PP1 1.1)

Contributed By: MK

Contact: Software Specialists  
Field Engineering  
Tempe Operations  
(602) 829-3100

Information Type:  
 Mandatory  
 As Needed  
 Information Only

\*\*\*\*\*

Symptom / Problem                      DATA I/O 29 PROM CORRECTIONS

The data I/O interface program on the EXORMacs, PP1.LO, is limited as the size of PROMs (expects maximum size of 8K by 8), and is only designed to work with the Data I/O System 17 or 19. Either the UNIPak or MOSpak may be used. Further, any part number terminating with an alpha character, such as INT2732A, is not understood by the program. The documentation in M68KDIOPP/D2 Section 1 Table 1-1 on page 4 gives the incorrect address locations for patching the manufacturer's part tables. Correction given below.

The following patches will: 1) enable PROMs greater than 8K by 8 to be read/programmed, 2) enable the INT2732A, INT27128, INT27256, and TMS74188A to be programmed, 3) enable a DATA I/O 29A to be used instead of a DATA I/O system 17 or 19, and 4) correct an error message.

\*\*\*\*\*

Solution / Fix

Documentation correction: M68KDIOPP/D2 Table 1-1 on p. 4

MCM - 14210/14218	MMI - 14352/1435A	74S - 1450A/14512
INT - 1425E/14266	HM- - 143E8/143FO	27S - 145B0/145B8
TMS - 1429C/142A4	B2S - 14466/1446E	FAR - 1462E/14636

Patches to PP1.LO:

=PATCH PP1.LO

M 12151	(3)	TO USE DATA I/O 29A
12151/32 37		DON'T USE FOR DATA I/O SYSTEM 19!!!!
.		
M 124E0	(1)	TO PROGRAM/READ PROMS GREATER THAN
124E0/3F 7F		8K BY 8
.		
M 1320F	(4)	TO CORRECT AN ERROR MESSAGE
1320F/B6 B1		(STRICTLY OPTIONAL)
.		
M 14251	(2A)	TO USE INT 2732A
14251/2A 20		(MUST ENTER PART NUMBER INT27320)
.		
M 14277	(2E)	TO USE TMS74188A
14277/8A 80		(MUST ENTER PART NUMBER TMS741880)
.		
M 1425E	(2C)	TO ADD TO INTEL TABLE:
1425E/00 1,2,71,28,40,0,35,51		INT27128
14266/00 0,2,72,56,80,0,93,32		INT27256

Q

=END

MICROSYSTEMS PRODUCT  
FIELD BULLETIN  
\*\*\*CONFIDENTIAL\*\*\*

Date: January 4, 1983

MPFB 0044

Product Type:  
Contact: Hardware Specialists  
Field Engineering  
Tempe Operations  
(602) 829-3100

Contributed By: PK  
Information Type:  
 Mandatory  
 As Needed  
 Information Only

\*\*\*\*\*

Symptom / Problem                      INCORRECT CHIP IN 68KDM

-----  
While running a program on the 68KDM the program appears to run away, or when reading data, the data is incorrect.

\*\*\*\*\*

Solution / Fix

Check U-83, it should be a 74S74 or a 54S74. On some boards, 7474 and 7479 were used. The 7474 and 7479 caused a conflict between the refresh cycle and the data fetch cycle. Sometimes it would use the refresh address to fetch program data. In the event you find one of these boards, set it up through one of the Coordinators to exchange it.

MICROSYSTEMS PRODUCT  
FIELD BULLETIN  
\*\*\*CONFIDENTIAL\*\*\*

Date: October 21, 1983

MPFB 0045

Product Type: VME/10 Show Demo  
Contact: Software Specialists  
Field Engineering  
Tempe Operations  
(602) 829-3100

Contributed By: PK  
Information Type:  
 Mandatory  
 As Needed  
 Information Only

\*\*\*\*\*  
Symptom / Problem                      VME/10 GRAPHICS DEMO INSTRUCTIONS

Lack of documentation on how to execute the VME/10 Graphics Demo.

\*\*\*\*\*  
Solution / Fix

1. After the system has been booted or reset, logon under the user number which contains the two demo files, SERVER.LO and VME10.LO.
2. To start the demonstration from VERSAdos, enter  
  =@SERVER  
to start the background server task, followed by  
  =VME10  
to start the foreground keyboard entry processor task.
3. The screen should display the Motorola logo over the function key definitions.
4. Depress F12 (function key 12) to clear the logo. The function key definitions will remain.
5. Select one of the following demos by depressing the associated function key:
  - F1 -- VME/10 demo loop
  - F2 -- HDS400 demo loop
  - F3 -- 68000 logo blink
  - F4 -- 68000 logo graphic slide
  - F5 -- Random lines graphic slide
  - F6 -- Colorfill cube graphic slide (black)
  - F7 -- Colorfill cube graphic slide (white)
  - F8 -- VME/10 uses slide
  - F9 -- VME/10 intro slide
  - F10-- Phoenix bird
  - F11-- Motorola logo
  - F12-- Clear screen (of graphics)

6. Types of demos by function key
  - a. F1, F2, F3 — demos run continuously, changing display demos with function key definition display off.
  - b. F4 thru F12 — demos run individual slides with function key definition display on.
7. To terminate a demo (by function key)
  - a. F1, F2, F3 — while running depress the BREAK key and F12.
  - b. F4, thru F12 — while running depress F12.
8. To return to VERSAdos after terminating a demo and clearing the graphics memory (depress F12), depress the following in sequence:
  - ESC key — the escape key, returns to VERSAdos with the background task still running. The prompt (=) will appear.
  - BREAK key — The break key, aborts the server task. The prompt (=) will appear.

(CAUTION: Failure to abort the server task with the break key will result in NEED TO REBOOT!!)

MICROSYSTEMS PRODUCT  
FIELD BULLETIN  
\*\*\*CONFIDENTIAL\*\*\*

Date: October 22, 1983

MPFB 0046

Product Type: VERSAdos 4.25 Disk Diagnostic  
Contact: Hardware Specialists  
Field Engineering  
Tempe Operations  
(602) 829-3100

Contributed By: JV and MM  
Information Type:  
\_\_\_ Mandatory  
\_x\_ As Needed  
\_\_\_ Information Only

\*\*\*\*\*

Symptom / Problem                      VME/10 DISK DIAGNOSTICS PATCH

-----  
The disk diagnostics for the VME/10, under VERSAdos 4.25, fail on drive 2 when the R1WIN board (01-W3130B01) is modified to revision 'T' or revision 'U' (the latest revision). The resident disk diagnostic will fail with 'HEADER ID NOT FOUND'. (SPR 871)

\*\*\*\*\*

Solution / Fix

The following chain file patches to the WDC user diagnostic test version 092883 only. The version number will be displayed at the rightmost portion of the WDC user diagnostic test when booted up.

```
=PATCH WDC.SY
M 43AFE;DI                      (Fix interrupt test for floppy drives)
MOVE.L #32,$1A18                (was MOVE.L #32,$1A1C)
MOVE.B #1,$19F0                (was MOVE.B #1,$19F6)

'1'                              (change revision date)
'0'                              (was '0')
'2'                              (was '2')
'0'                              (was '8')
.
Q
```

MICROSYSTEMS PRODUCT  
FIELD BULLETIN  
\*\*\*CONFIDENTIAL\*\*\*

Date: October 27, 1983

MPFB 0047

Product Type: EXORmacs and VMC with 50 Meg Lark    Contributed By DF

Contact: Hardware Specialists                      Information Type: --- As Needed  
          Field Engineering                            -X- Mandatory  
          Tempe Operations                            --- Information Only  
          (602) 829-3100

\*\*\*\*\*

Symptom / Problem                      50 MEG LARK DRIVES WITH 8 MEG CARTRIDGES

Customers who order "50" Megabyte Lark Disk Drives (for EXORmacs or VMC) are receiving 8 Megabyte Lark Cartridges. The problem is that the "50" Megabyte Lark Drives use a 25 Megabyte Cartridge. The Marketing Bill of Material currently calls for 8 Megabyte, since 25 Megabyte is not being produced yet (with the software on it).

\*\*\*\*\*

Solution / Fix

Ship a scratch 25 Megabyte Lark Cartridge to the customer.

To get the software off of the 8 Megabyte cartridge onto the 25 Megabyte cartridge, copy the software from the 8 Megabyte cartridge to the fixed media, then copy the software up to the 25 Megabyte cartridge.

MICROSYSTEMS PRODUCT  
FIELD BULLETIN  
\*\*\*CONFIDENTIAL\*\*\*

Date: November 2, 1983

MPFB 0048

Product Type: VERSAdos 2.1,3.0,4.1,4.2,4.25

Contributed By MM & SK

Contact: Hardware Specialists  
Field Engineering  
Tempe Operations  
(602) 829-3100

Information Type: --- As Needed  
-X- Mandatory  
--- Information Only

\*\*\*\*\*  
Symptom / Problem                                  DEBUGGING WITH MACSBUG

Some customers may wish to debug their software on an EXORMacs (without a USE or RDS or HDS) in the M68000's supervisory mode. This is possible in MACSbug on the EXORMacs if you can load the program into memory with VERSAdos and then go to MACSbug for debugging.

The following procedure for VERSAdos describes the process. To run in supervisory mode, the status register must be set up in MACSbug prior to program execution. NOTE that any exception processing will cause MACSbug to lose control of the program. Test exception processing routines by pushing data onto the stack and doing a jump indirect through the vector table.

\*\*\*\*\*  
Solution / Fix

PROCEDURE

- 1) Make sure you are the ONLY user on the EXORMacs. (Use sessions)
- 2) Under VERSAdos, load your program, '=LOAD filename'.
- 3) Use SYSANAL to determine the location of your program in memory. Enter SYSANAL. Type TASK filename.

The program is loaded at the address determined by adding the logical address to the Physical Offset.

The Logical address is in each segment under FR xxxxxx

The Physical Offset is in each segment under (PO xxxxxx)

- 4) Move the program to where it expects to execute and start debugging. To move the segment, you can use the following program, setting up the registers as indicated.  
22D8 LOOP MOVE.L (AO+,(A1)+ | AO=begin from address  
8089       CMP.L A1,DC | A1=begin destination addr  
6EFA       BGT.S LOOP | DO=ending destination addr + 1  
60FE END   BRA.S END | hit RESET again to gain control

MICROSYSTEMS PRODUCT  
FIELD BULLETIN  
\*\*\*CONFIDENTIAL\*\*\*

Date: November 1, 1983

MPFB 0049

Product Type: VME/10

Contributed By MK

Contact: Software Specialists  
Field Engineering  
Tempe Operations  
(602) 829-3100

Information Type: --- As Needed  
-X- Mandatory  
--- Information Only

\*\*\*\*\*  
Symptom / Problem                      ADDING MVME210 BOARD TO VME/10

VERSAdos 4.15 will not recognize any additional memory added to it unless a new sysgen is executed specifying the range of new memory, as detailed below.

\*\*\*\*\*  
Solution / Fix

The following procedure needs to be followed to add additional memory to the VME/10 and have VERSAdos understand that it is there.

1. Add a MVME210 board which is strapped to addresses in the range of \$180000 through \$DFFFFFF, the address range to be used for the VMEbug memory boards. In this example I have strapped the addresses to cover the range \$180000 through \$1BFFFF.
2. Modify SYS:9100.VME10.SYSCMD.SA to include two new parameters, MEMEND4 and MEMEND5, to define a new partition of VERSAdos memory.  
MEMEND1 = \$20000    Ceiling addr for part 0  
MEMEND2 = \$20000    Floor addr for part 1  
MEMEND3 = \$60000    Ceiling addr for part 1  
MEMEND4 = \$180000   Floor addr for part 2    \*\*add\*\*  
MEMEND5 = \$100000   Ceiling addr for part 2    \*\*add\*\*
3. Modify SYS:9100.VMES10.IND.SA to expand the memory allocation table using the MENTRY macro.  
MEMTABL    EQU            \*  
           MENTRY RAM,\$00000,/MEMEND1,MTYPO,PART0, TOP  
           IFNE            /MEMEND2  
           MENTRY RAM,/MEMEND2,/MEMEND3,MTYPO,PART1,BOTTOM  
           ENDC  
           IFNE            /MEMEND4                            \*\*add\*\*  
           MENTRY RAM,/MEMEND4,/MEMEND5,MTYPO,PART2, TOP    \*\*add\*\*  
           ENDC    \*\*add\*\*  
           MTEND  
           DS.L            10  
ENDMEMT    EQU            \*  
           END
4. Ensure that you are logged on under SYS:9100.& and then re-execute the sysgen command  
      =VMES10.SYSGEN.CF <args>  
      where <args> are as defined in the SYSGEN manual.





```

procedure num2str ( var num : integer; var str : str80 );
const base = 10
var quot, remainder, b: integer;
    total      : str80;
    select     : string[20];
    singl      : char;
begin
select := '0123456789ABCDEF';
b      := num;
if ( b < 0 ) then b := -b;
total  := '';
quot   := 1;
while (quot <> 0) do
begin
quot      := b div base;
remainder := b mod base;
sngl     := select[remainder+1];
total    := concat(sngl,total);
b        := quot
end;
str := total;
end;

begin
pass      := 1;
while (pass < 3 ) do
begin
count     := 0;
reset ( ifile );
if (pass = 2)
then begin
num2str ( alloc, options );
options := concat (';C=',options);
rewrite ( ofile, options );
end;
while (not eof(ifile)) do
begin
buffer    := ifile@;
get ( ifile );
count    := count + 1;
1 := 1;
while ( ( i < 128) and (buffer[i] = -1) ) do
i := i + 1;
if ( (i= 128) and ( pass = 1 ))
then count := count - 1;
if ( (i <> 128) and (pass = 2) )
then begin
ofile@ := buffer;
put (ofile)
end;
end;
pass := pass +1;
alloc := count;
end;
end.

```



MICROSYSTEMS PRODUCT  
FIELD BULLETIN  
\*\*\*CONFIDENTIAL\*\*\*

Date: October 27, 1983

MPFB 0052

Product Type: VME/10

Contributed By PK

Contact: Hardware Specialists  
Field Engineering  
Tempe Operations  
(602) 829-3100

Information Type: --- As Needed  
-X- Mandatory  
--- Information Only

\*\*\*\*\*

Symptom / Problem

VME10 REWIRE

Here are two more possible causes of soft errors.

\*\*\*\*\*

Solution / Fix

- (1) The batteries have two plugs associated with them, P1 and P2. Follow the gray and black pair back to the power supply, this should be P1. Remove the black wire from the connector, tape it off, and then tie it back out of the way. Replace P1 with the gray wire still on the inside of the power supply.
- (2) Remove the green wire from TB1 on the front of the power supply, and connect it to the 24v return line on TB2.

MICROSYSTEMS PRODUCT  
FIELD BULLETIN  
\*\*\*CONFIDENTIAL\*\*\*

Date: October 27, 1983

MPFB 0053

Product Type: VME/10

Contributed By PK

Contact: Hardware Specialists  
Field Engineering  
Tempe Operations  
(602) 829-3100

Information Type: --- As Needed  
-X- Mandatory  
--- Information Only

\*\*\*\*\*  
Symptom / Problem                      ONE ACKNOWLEDGE FOR 2 INTERRUPTS

Interrupts vectoring to the wrong places.

\*\*\*\*\*  
Solution / Fix

If you have an on-board interrupt and an off-board interrupt (of the same level) pending at the same time, the system could acknowledge both. With both interrupt sources putting their vector # on the bus at the same time the system vectors to an unknown address.

Fix: Replace the PROM at location U218.

Old P/N : 51AW1940x16  
New P/N : 51AW1940x18

MICROSYSTEMS PRODUCT  
FIELD BULLETIN  
\*\*\*CONFIDENTIAL\*\*\*

Date: November 1, 1983

MPFB 0054

Product Type: VME/10

Contributed By PK

Contact: Hardware Specialists  
Field Engineering  
Tempe Operations  
(602) 829-3100

Information Type: --- As Needed  
-X- Mandatory  
--- Information Only

\*\*\*\*\*

Symptom / Problem

KEYBOARD INITIALIZATION ERRORS

Keyboard Init errors during the power-up selftests, SCB.SY, and sometimes when loading VERSAdos.

\*\*\*\*\*

Solution / Fix

If you get a keyboard Init error, and you can still use the keyboard, chances are that the S/W or F/W is at fault. The reset line to the keyboard is S/W controlled and must be held low for a minimum of 3.0 usec. This problem has been patched out of VERSAdos 4.25, and has also been fixed by the new release of the SCB.SY diagnostic called SCM.SY; however, the power-up selftest still has this bug in it and will occasionally give you a K.B. Init error.

MICROSYSTEMS PRODUCT  
FIELD BULLETIN  
\*\*\*CONFIDENTIAL\*\*\*

Date: November 1, 1983

MPFB 0055

Product Type: VME/10

Contributed By PK

Contact: Hardware Specialists  
Field Engineering  
Tempe Operations  
(602) 829-3100

Information Type: --- As Needed  
-X- Mandatory  
--- Information Only

\*\*\*\*\*

Symptom / Problem

KEYBOARD TIMEOUT ERRORS

\*\*\*\*\*

Solution / Fix

Watch out for bad cables when you start getting the keyboard timeout error. Both the external and internal K.B. cables have some connectors that were poorly crimped. The best way to ohm out this problem is to take the VME/10 and the keyboard apart, and ohm from the connector on the inside of the keyboard to the connector on the VMEC1 board itself. This will ensure the integrity of the path from the keyboard to the system.

MICROSYSTEMS PRODUCT  
FIELD BULLETIN  
\*\*\*CONFIDENTIAL\*\*\*

Date: November 1, 1983

MPFB 0056

Product Type: VME/10

Contributed By PK

Contact: Hardware Specialists  
Field Engineering  
Tempe Operations  
(602) 829-3100

Information Type: --- As Needed  
-X- Mandatory  
--- Information Only

\*\*\*\*\*

Symptom / Problem

VME/10 EMPTY SCREEN ON POWER-UP

Sometimes, during the power-up sequence, the VME/10 fails to reset properly, and the system appears to be down. (There will be nothing on the screen.

\*\*\*\*\*

Solution / Fix

The mask in the MC68010 in some of the VME/10's has a bug in it. If it fails to reset correctly, try giving it a hard reset by depressing the reset button, tapping the abort button, and then releasing the reset button.



MICROSYSTEMS PRODUCT  
FIELD BULLETIN  
\*\*\*CONFIDENTIAL\*\*\*

Date: November 1, 1983

MPFB 0057

Product Type: VME/10

Contributed By PK

Contact: Hardware Specialists  
Field Engineering  
Tempe Operations  
(602) 829-3100

Information Type: --- As Needed  
-X- Mandatory  
--- Information Only

\*\*\*\*\*  
Symptom / Problem

SHIPPING MICROPOLIS = FLOPPY DISK DRIVES

\*\*\*\*\*  
Solution / Fix

The micropolis floppies were designed to be shipped without a shipping diskette in. They built in a switch that won't allow the heads to load if there wasn't a floppy in the drive. Damage and/or misalignment to the head can result if you use one.

MICROSYSTEMS PRODUCT  
FIELD BULLETIN  
\*\*\*CONFIDENTIAL\*\*\*

Date: November 1, 1983

MPFB 0058

Product Type: VME/10

Contributed By PK

Contact: Hardware Specialists  
Field Engineering  
Tempe Operations  
(602) 829-3100

Information Type: --- As Needed  
-X- Mandatory  
--- Information Only

\*\*\*\*\*  
Symptom / Problem                      JITTERY VME/10 MONITERS

THE DISPLAY IS JITTERY AND UNSTABLE.

\*\*\*\*\*  
Solution / Fix

TWO POSSIBILITIES

(1) In the factory, the monitors are adjusted when they are warm, so in some cases they become more stable as they warm up.

Fix : If this problem exists, the horizontal adjustment is on the hairy edge and a slight adjustment should get rid of the warm up time.

(2) After warm up the display stays unstable.

Fix : If boards were added in the back of the VME/10 the drain on the 5v supply has increased and the 24v supply is starting to give us some trouble. Again, adjust the horizontal pot in the monitor.

MICROSYSTEMS PRODUCT  
FIELD BULLETIN  
\*\*\*CONFIDENTIAL\*\*\*

Date: November 1, 1983

MPFB 0059

Product Type: VME/10

Contributed By PK

Contact: Hardware Specialists  
Field Engineering  
Tempe Operations  
(602) 829-3100

Information Type: --- As Needed  
-X- Mandatory  
--- Information Only

\*\*\*\*\*

Symptom / Problem                      VME/10 SCREEN PROBLEM

On some monitors the characters are so far to the right or left that they appear to wrap around behind the screen, and are displayed backwards.

\*\*\*\*\*

Solution / Fix

In most cases you can adjust this out with the horizontal pot.

MICROSYSTEMS PRODUCT  
FIELD BULLETIN  
\*\*\*CONFIDENTIAL\*\*\*

Date: November 1, 1983

MPFB 0060

Product Type: MVME110

Contributed By PK

Contact: Hardware Specialists  
Field Engineering  
Tempe Operations  
(602) 829-3100

Information Type: --- As Needed  
-X- Mandatory  
--- Information Only

\*\*\*\*\*  
Symptom / Problem                      SPURIOUS INTERRUPT TO VME110 BOARD

Spurious interrupts from the I/O channel. Intermittently the VME110 board receives an unsolicited interrupt from the I/O channel.

\*\*\*\*\*  
Solution / Fix

The resistor pack at location R17 which terminates the INT1-INT4 lines, on some VME110, was installed backwards and doesn't provide enough noise immunity. Pin 1 of R17 should go to ground and pin 8 should go to +5v. Power down the equipment and verify this with an ohmmeter.

MICROSYSTEMS PRODUCT  
FIELD BULLETIN  
\*\*\*CONFIDENTIAL\*\*\*

Date: November 1, 1983

MPFB 0061

Product Type: VME10

Contributed By PK

Contact: Hardware Specialists  
Field Engineering  
Tempe Operations  
(602) 829-3100

Information Type: --- As Needed  
-X- Mandatory  
--- Information Only

\*\*\*\*\*  
Symptom / Problem                      BUS ERROR ON VMEBUS

Trying to talk to boards on the VMEBUS results in a bus error.

\*\*\*\*\*  
Solution / Fix

This problem was determined to be a bad decoder prom in location u287. A new prom has been generated and the part #'s are as follows:

old p/n	51	aw4000B40
new p/n	51	aw4000B51

MICROSYSTEMS PRODUCT  
FIELD BULLETIN  
\*\*\* CONFIDENTIAL \*\*\*

Date: November 1, 1983

MPFB 0062

Product Type: VME10

Contributed By PK

Contact: Hardware Specialists  
Field Engineering  
Tempe Operations  
(602) 829-3100

Information Type: --- As Needed  
--- Mandatory  
-X- Information Only

\*\*\*\*\*

Symptom / Problem

KEY TO BATTERY BACKUP ON VME/10

The battery backup connector in the VME/10 isn't keyed very clearly.

\*\*\*\*\*

Solution / Fix

To assure the battery is connected correctly to the VMEC1 board check to see that the red wire goes to pin 1.

MICROSYSTEMS PRODUCT  
FIELD BULLETIN  
**\*\*\* CONFIDENTIAL \*\*\***

Date: October 27, 1983

MPFB 0063

Product Type: EXORmacs

Contributed By PK

Contact: Hardware Specialists  
 Field Engineering  
 Tempe Operations  
 (602) 829-3100

Information Type: --- As Needed  
 --- Mandatory  
 -X- Information Only

\*\*\*\*\*

Symptom / Problem VME/10 CHASSIS DOCUMENTATION ERROR

In the chassis user's manual on page 7-13 there is a pin-out of the debug printer cable for the EXORMACS. This pin-out is reversed. It should read as follows:

\*\*\*\*\*

Solution / Fix

It also says all odd # pins are ground. Not true. All even # pins are ground.

<u>REAR PANEL</u>	<u>P3</u>	<u>P2</u>
49	49	18
47	47	20
45	45	22
43	43	24
41	41	26
39	39	28
37	37	30
35	35	32
33	33	34
31	31	36
29	29	38
27	27	40
25	25	42
23	23	44
21	21	46
19	19	48
17	17	50
15	15	52
13	13	54
11	11	56
9	9	58
7	7	60
5	5	62
3	3	64
1	1	66

MICROSYSTEMS PRODUCT  
FIELD BULLETIN  
\*\*\*CONFIDENTIAL\*\*\*

Date: November 3, 1983

MPFB 0064

Product Type: EXORset 110

Contributed By CD & AZ

Contact: Hardware Specialists  
Field Engineering  
Tempe Operations  
(602) 829-3100

Information Type: --- As Needed  
--- Mandatory  
-X- Information Only

\*\*\*\*\*

Symptom / Problem

EXORSET 110 KEYBOARD PROBLEM

The Hyphen and underline key functions are transposed (lower case only).

\*\*\*\*\*

Solution / Fix

There is no contemplation fix to alter this transposition at this time. Just be aware of the condition, and appraise your customers accordingly.

Ref: Main Controller Module, U-125, I.C. SC80241P  
Part Number 51W9615G83



MICROSYSTEMS PRODUCT  
FIELD BULLETIN  
\*\*\*CONFIDENTIAL\*\*\*

Date: November 3, 1983

MPFB 0065

Product Type: VME/10

Contributed By PK

Contact: Hardware Specialists  
Field Engineering  
Tempe Operations  
(602) 829-3100

Information Type: --- As Needed  
--- Mandatory  
-X- Information Only

\*\*\*\*\*  
Symptom / Problem                      GROUNDS ON VME/10

One thing to try when getting excessive soft errors.

\*\*\*\*\*  
Solution / Fix  
In some of the VME/10's the AC and DC grounds are not isolated. The check out procedure is as follows:

Connect an ohmmeter from the top of the Winchester drive (DC ground) to the chassis (AC ground). This should read as an open. (To get good continuity on top of the wini, connect the ohmmeter to any screw holding the top to the wini.)

MICROSYSTEMS PRODUCT  
FIELD BULLETIN  
\*\*\*CONFIDENTIAL\*\*\*

Date: November 3, 1983

MPFB 0066

Product Type: VME/10

Contributed By PK

Contact: Hardware Specialists  
Field Engineering  
Tempe Operations  
(602) 829-3100

Information Type: -X- As Needed  
--- Mandatory  
--- Information Only

\*\*\*\*\*  
Symptom / Problem                      FLOPPY DISK LOOPING IN VME/10

Floppy hangs in a harmonic loop which results in soft errors.

\*\*\*\*\*  
Solution / Fix

Try adjusting the PLL as follows:

1. Connect a freq counter to E5 on the RWIN1 board.
2. Attach a shorting clip to u100 (clip shorts pin 12-16 and pin 11-8)
3. Adjust c54 until the frequency is between 7.4 and 7.5 Mhz.
4. If you cannot achieve this window adjust it to the lowest possible frequency, not to exceed 7.8 Mhz.

MPFD

MICROSYSTEMS PRODUCT

FIELD BULLETIN  
\*\*\*CONFIDENTIAL\*\*\*

Date: November 11, 1983

MPFB 0067

Product Type: VME/10

Contributed By: MM

Contact: Software Specialist  
Field Engineering  
Tempe Operations  
(602) 829-3100

Information Type:   x   As Needed  
       Mandatory  
       Information Only

\*\*\*\*\*

Symptom / Problem

WRITING TO VME/10 ON BOARD RAM

Setting bit 5 in control register 2, at address \$F19F09, allows the VMEbus to write to VME/10 on board RAM. This is useful when you have something like a VME110 that wants to write to VME/10 memory. The problem is that you must write to the register while in Supervisory mode of the MC68010 chip. If you write to it from User mode, such as from a user program under VERSAdos, the change appears to have taken place (if you then read the register you get what you wrote to it) but it in fact hasn't. Engineering is aware to the problem and will probably be fixing it later on, the problem appears to be in U216.

\*\*\*\*\*

Solution / Fix

The following program allows a VERSAdos program to change the byte at \$F19F09 while in Supervisory mode by using some Field Service Standard Practice Mysticism. We claim the timer interrupt vector for one timer tick, process the interrupt ourself, and restore the timer vector when done. Please keep the program as it is as several things present need to be there in order to work, such as the ORG to put the program into one MMU segment, the PC relative addressing in the SERVICE routine, etc.

	ORG	\$1000	
START	LEA	STACK,A7	SET UP STACK
	LEA	GTSEG,A0	ALLOCATE VECTOR TABLE TO PROGRAM
	MOVE.L	#1,D0	
	TRAP	#1	
	BNE	ABORT	
	LEA	RCVSA,A0	RECEIVE SEGMENT ATTRIBUTES W/ PHYS ADDR
	MOVE.L	#9,D0	
	TRAP	#1	
	BNE	ABORT	
	MOVE.L	#\$130,A0	SAVE CURRENT TIMER VECTOR
	MOVE.L	(A0),SAVEIT	
	MOVE.L	PHYS,D1	
	ADD.L	#SERVICE-START,D1	CALCULATE PHYSICAL SERVICE ADDRESS
	MOVE.L	D1,(A0)	STUFF ADDRESS INTO VECTOR TABLE
	MOVE.L	#0,FLAG	
WAIT	MOVE.L	FLAG,D0	
	BEQ.S	WAIT	SEE IF SERVICE ROUTINE IS DONE

EXIT	MOVE.L	#15,DO	RETURN TO VERSADOS
	TRAP	#1	
ABORT	MOVE.L	DO,AO	ABORT, BAD RETURN CODE FROM VERSADOS
	MOVE.L	#14,DO	
	TRAP	#1	
SERVICE	MOVE.L	AO,-(A7)	SAVE AO ON SYSTEM STACK
	MOVE.B	#\$B4,\$F19F09	DO THE MOVE TO THE CONTROL REGISTER NOW
	LEA	FLAG(PC),AO	SET CONTROL FLAG FOR SETUP TASK
	MOVE.L	#\$FF,(AO)	
	MOVE.L	#\$130,AO	
	MOVE.L	SAVEIT(PC),(AO)	RESTORE TIMER INTERRUPT VECTOR
	MOVE.L	(A7)+,AO	RESTORE AO
	RTE		
FLAG	DC.L	0	
SAVEIT	DC.L	0	
GTSEG	DC.L	0,0,\$01000800	
	DC.L	'MARK'	
	DC.L	\$130	
	DC.L	1023-\$130-1	
RCVSA	DC.L	0,0,\$4000000,0	
	DC.L	RCVSA,0,SEGMENT	
SEGMENT	DC.L	0	
	DC.L	0	
	DC.W	0	
	DC.L	0,0	
PHYS	DC.L	0	PHYSICAL ADDRESS OF THIS SEGMENT
	DCB.L	50,0	
STACK	DC.L	0	
	END	START	

# **NUMERIC INDEX**

November 21, 1983

Index for Microsystems Product Field Bulletin

Document Number	Description	Rev. Date
MPFB 0001	CDC 300 Hard Disk Install on EXORMacs	04/16/82
MPFB 0002	CDC Hard Disk Changes	04/22/82
MPFB 0003	Bypassing the CDC interblocks	04/15/83
MPFB 0004	MDOS and XDOS Firmware Modifications	11/16/82
MPFB 0005	Multi-Drop HDS-400 on EXORMacs	09/14/83
MPFB 0006	EXORMacs board rev levels as of 10/15/83	10/15/83
MPFB 0007	Maintenance Documentation Error	06/04/82
MPFB 0008	KDM to MCCM on EXORMacs	06/09/82
MPFB 0009	512K Memory Board Addressing	08/30/82
MPFB 0010	VERSAdos 3.0 LIST Utility Patch	05/17/82
MPFB 0011	VERSAdos 3.0 SPOOLER Utility Patch	05/17/82
MPFB 0012	68K SYMBUG Patch	05/17/82
MPFB 0013	VERSAdos 3.0 .FHS Call to Receive LU Patch	08/30/82
MPFB 0014	VERSAdos 3.0 Sysgen Corrections	09/01/82
MPFB 0015	DATA I/O 29 Personnel Contact	09/03/82
MPFB 0016	VERSAdos 2.1 & 3.0 Hardware Info Location	09/14/82
MPFB 0017	VERSAdos 3.0 MCCM 'Features'	10/14/82
MPFB 0018	Change MCCM Port for Modem Hook Up	10/15/82
MPFB 0019	VERSAdos 3.0 EDITOR Hang Up Patch	10/15/82
MPFB 0020	MCCM General Info and Errata	08/01/83
MPFB 0021	Resetting SECTOR 0 to Point to IPL	08/01/83
MPFB 0022	Analyzing a Crashed VDDS on VMC or EXORmac	08/01/83
MPFB 0023	Known Bugs/Cautions with SYMBUG/A	08/01/83
MPFB 0024	VDOS 4.1/4.2/4.21 MCCM Device Control Blk	08/03/83
MPFB 0025	LINKing a Program on a NON-MMU System	09/23/83
MPFB 0026	VME200/201 Address Decoding Problems	01/26/83
MPFB 0027	MDOS 2MHZ Format Patch	04/16/82
MPFB 0028	RLOAD for 6809. (Version 3.10, 3.11)	04/16/82
MPFB 0029	10 Ways to Crash 6809 With Trace	04/16/82
MPFB 0030	EXORset 35 High Temperature Warnings	09/09/82
MPFB 0031	EXORset 35 Malfunction Correction	11/05/82
MPFB 0032	Rejumper VME400 on VME/10	09/19/83
MPFB 0033	Patch to Allow Breakpoints on VM02	09/23/83
MPFB 0034	AF Crash on VERSAdos at Logon	10/13/83
MPFB 0035	VERSAdos 4.1 Initialize Memory Requirement	10/17/83
MPFB 0036	VMC 68/2 Problems and Solutions	10/17/83
MPFB 0037	ASCII File Transfer (2.00) Problem	10/17/83
MPFB 0038	VERSAdos 4.x Change Name of #PR to #PR1	10/17/83
MPFB 0039	VERSAdos 4.25 UPLOADS problem	10/17/83
MPFB 0040	VERSAdos 4.2 NODEFVOLS = NOLOGNS	10/17/83
MPFB 0041	Adding Multi-Drop HDS-400's on VDDS 4.21	10/13/83
MPFB 0042	SPOOLER Patch for VERSAdos 4.1 & 4.2	10/19/83
MPFB 0043	DATA I/O 29 Prom Corrections	10/19/83

November 21, 1983

Index for Microsystems Product Field Bulletin

pp2

---

Document Number	Description	Rev. Date
MPFB 0044	Incorrect Chip in 68KDM	01/04/83
MPFB 0045	VME/10 Graphics Demo Instructions	10/20/83
MPFB 0046	VME/10 Disk Diagnostics Patch	10/22/83
MPFB 0047	50 Meg Lark Drives with 8 Meg Cartridges	10/23/83
MPFB 0048	Debugging with MACSbug	11/02/83
MPFB 0049	Adding MVME210 Board to VME/10	11/01/83
MPFB 0050	Verify DB Error on SYMBUG Under VDOS 4.2	10/26/83
MPFB 0051	VM80 Interrupt Acknowledge	10/27/83
MPFB 0052	VME/10 Rewire	10/27/83
MPFB 0053	One Acknowledge for 2 Interrupts	10/27/83
MPFB 0054	Keyboard Initialization Errors	11/01/83
MPFB 0055	Keyboard Timeout Errors	11/01/83
MPFB 0056	VME/10 Empty Screen on Power-Up	11/01/83
MPFB 0057	Shipping Micropolis Floppy Disk Drives	11/01/83
MPFB 0058	Jittery VME/10 Monitors	11/01/83
MPFB 0059	VME/10 Screen Problem	11/01/83
MPFB 0060	Spurious Interrupt to VME110 Board	11/01/83
MPFB 0061	Bus Error on VMEbug	11/01/83
MPFB 0062	Key to Battery Backup on VME/10	11/01/83
MPFB 0063	VME/10 Chassis Documentation Error	10/27/83
MPFB 0064	EXORset 110 Keyboard Problem	11/03/83
MPFB 0065	Grounds on VME/10	11/03/83
MPFB 0066	Floppy Disk Looping in VME/10	11/03/83
MPFB 0067	Writing to VME/10 on Board RAM	11/11/83

**ALPHABETIC  
CROSS  
INDEX**



November 21, 1983

Cross Index for Microsystems Product Field Bulletin

---

Absolute Filter,

Air Flow Sensor - MPFB0003  
On CDC Hard Disk Drives, Changes - MPFB0002

ASCII File Transfer,

Error In Transfer 2.00 - MPFB0037  
MCCM Undocumented Features - MPFB0017

Battery Backup,

VME/10 Rewire - MPFB0052  
Key to Battery Backup on VME/10 - MPFB0062

Bus Trap Errors,

512K Board Addressing In EXORMacs - MPFB0009  
Bus errors on VMEbus - MPFB0061

Booting,

General Information and Problems on VMC 68/2 - MPFB0036  
Unable to Boot on VERSAdos 4.1 - MPFB0035

CDC Disk Drives,

CDC Hard Disk Changes - MPFB0002  
CDC Interlocks, How To Bypass - MPFB0003  
CDC 300 Megabyte Disk Drive Installation - MPFB0001

Crash and Crash Analysis,

Analyzing A Crashed VERSAdos - MPFB0022  
Logon Causing Crash - MPFB0034  
Unable To Log All Users Onto System - MPFB0040

CRTDCB,

Patching To Reconfigure the MCCM Ports - MPFB0024

Data I/O,

DATA I/O System 29 Personnel Contact - MPFB0015  
PROM Programmer PP1 On EXORMacs Patches - MPFB0043

Debug,

Board, EXORMacs Revision Level - MPFB0006  
Printer Name Change From VERSAdos 3. - MPFB0038  
ROM Chips For EXORMacs Debug Board - MPFB0007  
6309 Trace Problems - MPFB0029

Deckdown Switch,

CDC Interlocks, How To Bypass - MPFB0003

Diagnostic,  
VME/10 Disk Diagnostic Patch- MPFB0046

DIM,  
Board, EXORmacs Revision Level - MPFB0006

Documentation,  
VME/10 Chassis Documentation Error - MPFB0073

Editor,  
VERSAdos 3.0 CRT Editor Hangup Patch - MPFB0019

Electronics Module,  
On CDC Hard Disk Drives, Changes - MPFB0002

EXORDisk II/III,  
MDOS and XDOS Firmware Modifications - MPFB0004

EXORciser,  
RLOAD for 6809 - MPFB0028  
6809 Trace Problems - MPFB0029

EXORmacs,  
Connecting KDM to EXORmacs via MCCM - MPFB0008  
512K Board Addressing In EXORmacs - MPFB0009

EXORset,  
EXORset 35 High Temperature Warning - MPFB0030  
EXORset 35 Malfunction Correction - MPFB0031  
EXORset 110 Keyboard problem - MPFB0064

FOC,  
Board, EXORmacs Revision Level - MPFB0006

FHS,  
VERSAdos 3.0 FHS Receive Logical Units Patch - MPFB0013

FLOPPY DISK DRIVES,  
Shipping Micropolis Floppy Disk Drives - MPFB0057  
Floppy Disk Looping in VME/10 - MPFB0066

FORMAT,  
MDOS and XDOS Firmware Modifications - MPFB0004.  
MDOS 2MHz FORMAT Patch - MPFB0027

FORTRAN,  
RLOAD for 6809 - MPFB0028

GRAPHIC DEMO,  
Instructions to Execute VME/10 Graphics Demo - MPFB0045

GROUND,

Grounds on VME/10 - MPFB0065

HDS-400,

Error In Transfer 2.00 - MPFB0037

Multi-Drop On VERSAdos 4.21 Patch To GHOST - MPFB0005

Software Changes Needed for Multi-Drop HDS-400 Operation - MPFB0041

Unable to Boot on VERSAdos 4.1 - MPFB0035

Interlocks,

CDC Interlocks, How to Bypass - MPFB0003

Interrupt,

One acknowledge for 2 interrupts - MPFB0053

Claim interrupt to write to VME/10 on Board RAM - MPFB0067

INIT,

General Information and Problems on VMC 68/2 - MPFB0036

IDS,

Logon Causing Crash - MPFB0034

IPL,

Resetting Sector Zero to Point to IPL.SY - MPFB0021

Unable to Boot on VERSAdos 4.1 - MPFB0035

KDM Module,

Connecting KDM to EXORmacs via MCCM - MPFB0008

Incorrect Chip in 68KDM - MPFB0044

Keyboard,

Keyboard initialization Errors on VME/10 - MPFB0054

Keyboard Timeout Errors - MPFB0055

EXORset 110 Keyboard Problem - MPFB0064

LARK DRIVE,

50 Meg Lark Drive with 8 Meg Cartridges - MPFB0047

LIST,

VERSAdos 3.0 LIST Utility Patch - MPFB0010

Linkage Editor,

RLOAD for 6809 - MPFB0028

Special Handling in Non-MMU Systems - MPFB0025

MACSbug Debugging

Debugging with MACSbug - MPFB0048

Magnetic Pickup Switch,

CDC Interlocks, How to Bypass - MPFB0003

CCM,

Board, EXORmacs Revision level - MPFB0006  
Connecting KDM to EXORmacs Via MCCM - MPFB0008  
DATA I/O System 29 Personnel Contact - MPFB0015  
General Information - MPFB0020  
Modem Hookup Notes Under VERSAdos 3.0 - MPFB018  
Patching to Reconfigure the MCCM Ports - MPFB0024  
Printer Name Change from VERSAdos 3.0 - MPFB0038  
Undocumented Features - MPFB0017

MDOS,

MDOS and XDOS Firmware Modifications - MPFB0004  
MDOS 2MHz FORMAT Patch - MPFB0027

Memory Boards,

Boards, EXORmacs Revision Level - MPFB0006  
VME200/201 Address Decoding Problems - MPFB0026  
512K Board Addressing In EXORmacs - MPFB0009

Modem,

Modem Hookup Notes Under VERSAdos 3.0 - MPFB0018

MMU,

Special Handling in Non-MMU Systems - MPFB0025

MPU,

Board, EXORmacs Revision Level - MPFB0006  
VM80 Interrupt Acknowledge - MPFB0051

Multi-Drop,

HDS-400 On VERSAdos 4.21 Patch to GHOST - MPFB0005  
Software Changes Needed For Multi-Drop HDS-400 Operation - MPFB0041

MULTIHDS.CF,

Software Changes Needed for Multi-Drop HDS-400 Operation - MPFB0041

PAT,

Logon Causing Crash - MPFB0034

Patches,

ASCII File Transfer 2.00 Patch - MPFB0037  
Editor Hang Up Patch, VERSAdos 3.0 - MPFB0019  
FHS Patch, VERSAdos 3.0 - MPFB0013  
FORMAT Patch, MDOS - MPFB0027  
GHOST Patch, VERSAdos 4.21 - MPFB0005  
HDS-400 Patch, VERSAdos 4.21 - MPFB0005  
IPL Patch for Sector 0 on VERSAdos - MPFB0021  
LIST Patch, VERSAdos 3.0 - MPFB0010  
MDOS FORMAT Patch - MPFB0027  
PROM Programmer PP1 On EXORmacs Patches - MPFB0043  
SPOOLER Patch, VERSAdos 3.0 - MPFB0011  
SPOOLER Patch, VERSAdos 4.1, 4.2 - MPFB0042  
SYMBUG/A Patches, VERSAdos 3.0, 4.1, 4.2, 4.21 - MPFB0012, MPFB0023  
VERSAdos Patching for Breakpoints - MPFB0033  
VERSAdos 2.1, 3.0 Configuration Patches - MPFB0016  
VERSAdos 3.0 Patches for Modem - MPFB0018  
VERSAdos 4.1, 4.2, 4.21 Configuration Patches - MPFB0024  
VERSAdos 4.2 to Run Under VMcbug Patches - MPFB0033  
VME/10 Disk Diagnostic Patch - MPFB0043

PP1,

PROM Programmer PP1 On EXORMacs Patches - MPFB0043  
See Also: Data I/O

Printer Driver,

MDOS and XDOS Firmware Modifications - MPFB0004  
Printer Name Change From VERSAdos 3.0 - MPFB0038

Revision Levels,

On All EXORMacs Boards - MPFB0006

RLOAD,

RLOAD for 6809 - MPFB0008

R1WIN Board,

VME/10 Disk Diagnostic Patch - MPFB0046

SPOOLER,

VERSAdos 3.0 Spooler Patch - MPFB0011  
SPOOLER Patch, VERSAdos 4.1, 4.2 - MPFB0042

SUPERVISORY MODE,

Debugging with MACSbug in supervisory mode - MPFB0048  
Program to Write to VME/10 on board RAM Runs in Supervisory Mode - MPFB0067

SYMBUG/A 2.00'

Known Bugs, Cautions, Patches - MPFB0023  
SYMBUG Task Command Patch - MPFB0012  
Verify DB Error in Symoug - MPFB0050

SYSANAL,

Patching to Reconfigure the MCCM Ports - MPFB0024  
Used to find a tasks location in memory

SYSGEN,

General Information and Problems on VMC 68/2 - MPFB0036  
Logon Causing Crash - MPFB0034  
Modem Hookup Notes Under VERSAdos 3.0 - MPFB0018  
Patching to Reconfigure the MCCM Ports - MPFB0024  
Software Changes Needed for Multi-Drop HDS-400 Operation - MPFB0041  
Unable to Log All Users Onto System - MPFB0040  
VERSAdos 3.0 SYSGEN Corrections to IOC.SA - MPFB0014  
Adding a VME210 Memory Board to the VME/10 - MPFB0049

UIPC,

Board, EXORMacs Revision Level - MPFB0006

UPLOADS,

VERSAdos 4.25 UPLOADS from VME110 - MPFB0039

VERSAdos 2.1,

Resetting Sector Zero to Point to IPL.SY - MPFB0021  
Patch Addresses for Configuration Changes - MPFB0016  
Locating a Task in Memory - MPFB0048

VERSAdos 3.0,

Analyzing A Crashed VERSAdos - MPFB0022  
Connecting KDM to EXORMacs Via MCCM - MPFB0008  
CRT Editor Hangup Problem Patch - MPFB0019  
MCCM Undocumented Features - MPFB0017  
Modem Hookup Notes Under VERSAdos 3.0 - MPFB0018  
Patch Addresses for Configuration Changes - MPFB0016  
SYSGEN Corrections to IOC.SA - MPFB0014  
Locating a task in memory - MPFB0048

VERSAdos 4.1,

Analyzing a Crashed VERSAdos - MPFB0022  
Error in Transfer 2.00 - MPFB0037  
General Information and Problems on VMC 68/2 - MPFB0036  
Logon Causing Crash - MPFB0034  
Patch to LVCT Table - MPFB0033  
Patching to Reconfigure the MCCM Ports - MPFB0024  
Printer Name Change From VERSAdos 3.0 - MPFB0038  
Resetting Sector Zero to Point to IPL.SY - MPFB0021  
SPOOLER Patch, VERSAdos 4.1, 4.2 - MPFB0042  
Unable to Boot on VERSAdos 4.1 - MPFB0035  
Locating a Task in Memory - MPFB0048

VERSADOS 4.2,

Analyzing a Crashed VERSAdos - MPFB0022  
Logon Causing Crash - MPFB0034  
Patch to !VCT Table - MPFB0033  
Patching to Reconfigure the MCCM Ports - MPFB0024  
Printer Name Change from VERSAdos 3.0 - MPFB0038  
Resetting Sector Zero to Point to IPL.SY - MPFB0021  
SPOOLER Patch, VERSAdos 4.1, 4.2 - MPFB0042  
Unable to Log All Users Onto System - MPFB0040  
Locating a Task in Memory - MPFB0048  
Verify DB Error in Symoug - MPFB0050

VERSAdos 4.21,

Analyzing a Crashed VERSAdos - MPFB0022  
Patch to VCT Table - MPFB0033  
Patching to Reconfigure the MCCM Ports - MPFB0024  
Printer Name Change from VERSAdos 3.0 - MPFB0038  
Resetting Sector Zero to Point to IPL.SY - MPFB0021  
Software Changes Needed for Multi-Drop HDS-400 Operation - MPFB0041  
SPOOLER Patch, VERSAdos 4.1, 4.2 - MPFB0042  
Locating a Task in Memory - MPFB0048  
Verify DB Error in Symbug - MPFB0050

VERSAdos 4.25,

Resetting Sector Zero To Point to IPL.SY - MPFB0021  
UPLOADS From VME110 - MPFB0039  
Graphics Demo Instructions - MPFB0045  
VME/10 Disk Diagnostic Patch - MPFB0046  
Locating a Task in Memory - MPFB0048  
Adding a VME210 Memory Board to the VME/10 - MPFB0049  
Writing to VME/10 on Board RAM - MPFB0067

VMC 68/2,

Error In Transfer 2.00 - MPFB0037  
General Information and Problems - MPFB0036

VM80

VM80 Interrupt Acknowledge - MPFB0051

VME110,

VERSAdos 4.25 UPLOADS From VME110 - MPFB0039  
Spurious Interrupt to VME110 Board - MPFB0060

VMEBUS,

Bus Errors on VMEbus - MPFB0051

VME/10,

Adding a VME400 Board To A VME/10 - MPFB0032  
VERSAdos 4.25 UPLOADS From VME110 - MPFB0039  
VME/10 Disk Diagnostic Patch - MPFB0046  
Graphics Demo Instructions - MPFB0045  
VME/10 rewire - MPFB0052  
One acknowledge for 2 interrupts - MPFB0053  
Keyboard initialization errors on VME/10 - MPFB0054  
Keyboard Timeout Errors - MPFB0055  
VME/10 Blank Screen on Power-Up MPFB0056  
Shipping Micropolis Floppy Disk Drives - MPFB0057  
Jittery VME/10 Monitors - MPFB0058  
VME/10 Screen Problem, Character Wrap Around - MPFB0059  
Bus Errors on VMEbus - MPFB0061  
Key to Battery Backup on VME/10 - MPFB0062  
VME/10 Chassis Documentation Error - MPFB0063  
Grounds on VME/10 - MPFB0065  
Floppy Disk Looping in VME/10 - MPFB0066  
Writing to VME/10 on Board RAM - MPFB0067  
See Also: VERSAdos 4.25

ME200/201,

VME200/201 Address Decoding Problems - MPFB0026

VME210,

Adding a VME210 Memory Board to the VME/10 - MPFB0049

VME400,

Adding A VME400 Board to a VME/10 - MPFB0032  
VERSAdos 4.25 UPLOADS From VME110 - MPFB0039

XDOS,

MDOS and XDOS Firmware Modifications - MPFB0004

128K Memory Board,

Board, EXORmacs Revision Level - MPFB0006  
Board Addressing In EXORmacs - MPFB0009  
ADDING A VME210 Memory Board to the VME/10 - MPFB0049

256-512K Memory Board,

Board, EXORmacs Revision Level - MPFB0006  
Board Addressing In EXORmacs - MPFB0009  
Adding a VME210 memory board to the VME/10 - MPFB0049